

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20235206
Address: 2971 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Khanh Nguyen	Failed	Wednesday, March 25, 2026

Corrective Action Required:

1 Misc Garage PHF portal walls framing-OK to cover

**install blockings under window jack and kings studs

Corrective Action Required:

2 LOWER LEVEL OK:
-Pre-rock for corridor ceiling

**Pre-rock at showers and tubs corrections:

007:
-Strap over-bored top plate per plan

Corrective Action Required:

3 FIRST FLOOR OK:
-Pre-rock for corridor ceiling
-Pre-rock at showers and tubs
-Balconies- 106, Rafter has no bearing at top at middle of soffit
All others framing ok

Corrective Action Required:

4 SECOND FLOOR OK:
-Pre-rock for corridor ceiling
-Pre-rock at showers and tubs
-Balconies

Common deficiencies:

-Fc 4" or bigger roof drain penetrations at subfloor

218:

217:

215:

213:

216:

214:

-Protect back-back boxes near laundry standpipe; secure wiring near box

211:

212:

209:

-Fb fur out wall in bedroom; fb gap between wall top plates

210:

-Complete fur out wall at 6" roof drain **install top lid

207:

-Mud and fire tape elevator firewall. Close off excessive gaps and install fire tape

208:

205:

-Protect wiring at top plate near SE cable

206:

-Protect back-back boxes

-Screw down the floor-floor screw in bedroom

204:

-Protect wiring at kitchen top plate

-Fc holes at stair wall plate **holes about 3-3.5 ft left of mechanical closet door

203:

-Protect fire sprinkler at top wall plate in closet

201:

200:

- Provide hanger support for trusses where bearing is less than 1.5" of bearing
**above master bathroom
- Protect sprinkler pipe in bedroom **at top plate

Corrective Action Required:

5 THIRD FLOOR

OK:

- Pre-rock for corridor ceiling
- Pre-rock at showers and tubs
- Balconies

**Correction:

- Protect wiring at top plates where within 1.25" of nailing surface

Corrective Action Required:

6 FOURTH FLOOR

OK:

- Pre-rock for walls at showers and tubs
- Balconies
- Units, corridor

**Correction:

- Install GB at ceiling of dead space adjacent to storage space. Fire-stop penetration

Corrective Action Required:

7 ELEVATOR 1

OK:

- Pre-rock for top lid and wall

Comments: