

Tel +1 913 310 1600 intertek.com/building



## **FINAL SPECIAL INSPECTION REPORT**

Project Name:_	LBP V- A	Permit No. PRCOM20170788							
Project Address	s: 2900 NE Independence Ave, Lee's Summit, N	Missouri 64064							
Company Name	e: Professional Service Industries, Inc.	PSI Project No. <u>03532506</u>							
	y that I or a qualified individual working under the hostion 1704 of the International Building Co	my direction inspected and/or tested the following items in de.							
Prepared Fill Site Fill Stea	l e (Pad) Preparation Placement (LVC) aluation of In-Place Density	<ul><li></li></ul>							
✓ Verification (	of Soils (Shallow Foundations)	Steel Construction							
☐ Drilled Piers	and/or Piles	☐ Inspection of Steel Fabrication ☐ Steel Erection							
⊠ Pla □ For	nstruction Interials Inspection of Concrete Strength Inspection of Proper Mix Interials Interial	Installation of High Strength Bolt  Seismic-Sensitivity System Column Splice Welds Base Metal Testing  Wood Construction  Other: Post-Installed Adhesive Dowels							
	Erection of Precast Tilt-Up  e best of my knowledge is complete and was form applicable building codes.	ound to be in substantial compliance with the City plans,							
Signed: William	tha & Odell n E. Odell, P.E.	Date: <u>December 31, 2019</u>							
Submitted to:	<pre><khanh.nguyen@cityofls.net> Codes Administration 220 SE Green Street Lee's Summit, Missouri 64063</khanh.nguyen@cityofls.net></pre>	WILLIAM E  ODELL  WILLIAM E  ODELL  F-22563  F-22563  PROFESSIONAL  SERESPRENTESIONAL  21 19							



## SUMMARY OF DISCREPANCIES

LBP V-A Building Addition Lee's Summit, MO 03532506 City, State: PSI Project No. Project Name:

Through Report Date: October 11, 2017 Page 1 of 1

	DATE RESOLVED	12/31/2019	12/31/2019	12/31/2019	12/31/2019							
	RESOLUTION	Accepted as-built in sealed letter from Earl Rollison, PE dated 12/31/2019	Accepted as-built in sealed letter from Earl Rollison, PE dated 12/31/2019	Accepted as-built in sealed letter from Earl Rollison, PE dated 12/31/2019	Accepted as-built in sealed letter from Earl Rollison, PE dated 12/31/2019			77.00				
	DISCREPANCY	Post-installed installation of dowels into existing structure were not Special inspected.	PSI was not requested and did not provide any slab reinforcing steel observation or slab concrete testing.	PSI was not requested and did not provide any wall backfill testing.	PSI was not requested and did not provide any inspection of the tilt-up wall erection							
	LOCATION	Footing tie-ins to existing structure at F/2.2 & F/6.	Building addition slab-on-grade	All below grade tilt-up walls detailed on F2.2	All tilt-up wall panel to foundation or panel to panel connections							
	REPORT No.	RSI:03532506-5	Post Construction	Post Construction	Post Construction							
	DATE	5/16/2017	12/30/2019	12/30/2019	12/30/2019							
	No.	1	2	Э	4						-	



December 31, 2019

Mr. William Odell Intertek-PSI 1211 W. Cambridge Circle Drive Kansas City, KS 66103

Re: LBP V-A

Mr. Odell,

This letter is in regards to you Discrepancy report dated December 30, 2019. The items listed below are keyed into your discrepancy numbers:

- 1. The post installed dowel locations that were not observed is where the new continuous footing is doweled into the existing continuous footing. The dowels were to be epoxied into the existing footing. Per our phone conversation your inspector observed the bars were installed in one location, but, the installation was not observed by you inspector. Since the dowels are acting in shear only and to tie the footings together the dowels as installed are acceptable.
- 2. The slab on grade is a 6" thick. The use of the space at this time is for office loading. The mesh can be omitted in slab on grade. Since the in situ strength is not known at this time the owner will need to field verify the strength of the concrete for a use other than an office. The slab as placed in our opinion is acceptable.
- 3. I visited the site to observe a location of the holdown as specified on the tilt drawings. The anchor (3/4" diameter Titan HD concrete screw) was removed to verify the length. The concrete exceeds specified length. The use of the holdown's specified for the contractor to anchor the panel to the footing as during erection. The anchor is then installed once the panel is in its final location. It is our opinion that the anchors are in installed the panels.
- 4. During my site visit I also observed the panel to panel connections. The panel to panel connections are welded per our tilt drawings. There are a couple of corner locations where embeds were missing on one panel. The contractor installed a 3/4" expansion bolt. This is an acceptable solution.

If you have any questions do not hesitate to call.

Sincerely,

Earl V. Rollison P.E

Cc. Mr. Justin Bridges, Davisson A+E Cc. Mr. Doug Rothfus, Capital Construction

End V. Kaff