

1200 SE Hamblen Road | Lee's Summit, MO 64081

Backflow Prevention Assembly Test Data & Maintenance Report

- addition restaurant restaurant and a manifest and	
Reele-Nichols	
217 SW main 5t Lee's Sunnit MO 64081	
Location of Backflow Assembly on Property	
15tfloor mechanical room behindelyvator	
Date of Test Supply Pressure PM Supply Pressure B LBS	Air Gap (2 x Supply Diameter) Supply: IN. Gap: IN. Tall Gap PASS FAIL
Type of Assembly Manufacturer	Model Size Serial Number
DC RP DCDA (Detector) RPDA (Detector) PVB* (See Bottom of Form)	LF009M2RT 111 1962584
Height off Floor Protection From	Supply Source New Installation
FT IN Freezing: Ves No Flooding: Yes No	Public Potable Water Both Non-Potable Water (e.g., LAKE)
Inital Test Passed Failed	Final Test After Repair Passed Failed
Reduced Pressure Principle Assembly:	Reduced Pressure Principle Assembly:
RELIEF VALVE opened at PSID (2 PSID or more)	RELIEF VALVE opened at PSID (2 PSID or more)
2nd CHECK held backpressure	2nd CHECK held backpressure
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight
1st CHECK held in direction of flow 9,5 PSID (5 PSID or more)	
	1st CHECK held in direction of flow PSID (5 PSID or more)
DIFFERENCE (1st check - relief) PSID (3 PSID or more)	DIFFERENCE (1st check - relief) PSID (3 PSID or more)
Note: Failure of any of the above items, requires repair.	Note: Failure of any of the above items, requires repair.
Initial Test Passed Failed Double Check Valve Assembly:	Final Test After Repair Passed Failed Double Check Valve Assembly:
4 - 0.1504 11: 1: 1: 1: 1: 1: 1: 1: 1: 1: 1: 1: 1:	
	1st CHECK held in direction of flow PSID (1 PSID or more)
2nd CHECK held backpressure	2nd CHECK held backpressure
2nd CHECK held in direction of flowPSID (1 PSID or more)	2nd CHECK held in direction of flowPSID (1 PSID or more)
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight
Note: Failure of any of the above items, requires repair. Note: Failure of any of the above items, requires repair.	
Application: Comments	
Commercial	
☐ Irrigation	
Fire Line	
Fire Line By-Pass	
**Meter #	
**Meter Read	
Point of Use	
The Above Report is Certified to be True, Accurate and Complete	
Tested By (Print) (Signature)	Repaired by (Print) (Signature) Date of Repair
David Blixt WORK	
Levtury Plumbin	Final Test By (Print) (Signature) Date of Final Test
Missouri Certification Number Expiration Date	Owner or Owner's Representative Date
14-6009 12-31-2021	· ·
*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations.	
New PVB installations or replacements are not permitted. **METER # and METER READ for the fire line by-pass meter on detector assemblies are required.	

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.