## WATER UTILITIES LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

## **Backflow Prevention Assembly Test Data & Maintenance Report**

New Mark Homes					
1905 SW River Run Drive					
Location of Backflow Assembly on Property					
Date of, Test Time AMD Supply Pressure   Air Gap (2 x Supply Diameter)					
Right hand Side of to Date of, Test Time AME 8/27/2021 11:00 PM	LBS	Supply: IN. Gap: IN.		PASS	FAIL
Type of Assembly  DC RP	Manufacturer	Model	Size	Serial Number	
DCDA (Detector) RPDA (Detector)  PVB* (See Bottom of Form)	Febro	850	3/4 HE	69817	
Height off Floor Protection From		Supply Source New Installation			
FTIN Freezing: Yes No	Flooding: Yes No	Public Potable Non-Potable V	Water	YES	NO
Inital Test Passed Failed		Final Test After Repair Passed Failed			
Reduced Pressure Principle Assembly:		Reduced Pressure Principle Assembly:			
			PSID (2 PSID or more)		
2nd CHECK held backpressure	2nd CHECK held backpressure				
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight  1st CHECK held in direction of flow PSID (5 PSID or more)				
1st CHECK held in direction of flow PSID (5 PSID (5 PSID (5 PSID (5 PSID or more))	DIFFERENCE (1st check - relief) PSID (3 PSID or more)				
DIFFERENCE (1st check - relief) PSID (3 PSID or mor Note: Failure of any of the above items, requires					
Initial Test	Final Test After Repair		Passed	Failed	
Double Check Valve Assembly:  1st CHECK held in direction of flow 2, / PSID (1 PSID)	Double Check Valve Assembly:  1st CHECK held in direction of flow PSID (1 PSID or more)				
2nd CHECK held backpressure	2nd CHECK held backpressure				
2nd CHECK held in direction of flow / 8 PSID (1.8	2nd CHECK held in direction of flow PSID (1 PSID or more)				
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight				
Note: Failure of any of the above items, requires	Note: Failure of any of the above items, requires repair.				
Application:	Comments				
Commercial					
Irrigation					
Fire Line					
Fire Line By-Pass					
**Meter #				-	
**Meter Read					
Point of Use					
The Above Report is Certified to be True, Accurate and Complete					
Tested By (Print) (Signature)	Repaired by (Print)	(Signature)	Date of Repair		
Raymond Graber My TB Company Hernes Landsuping		Final Test By (Print)	(Signature)	Date of Final Test	
Hernes Landscroins	,				
Missouri Certification Number Expiration Date		Owner or Owner's Representative Date			
33-12089					
*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations.					
New PVB installations or replacements are not permitted.  **METER # and METER READ for the fire line by-pass meter on detector assemblies are required.					

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.