

June 10, 2022

Summit Homes 120 SE 30th St. Lee's Summit, MO 64082

RE: Field Issue of over-driven nails and incorrect nail pattern for Lot #12 Hawthorne Ridge – 2950 Arboridge Lee's Summit, MO 64082 - Permit # PRRES20214363


Findings:

- Dining room requires engineered bracing with 8d nails @ 3" oc at top and bottom of rim joist.
- More nails were fastened than required with a some nails being over-driven.

Recommendations:

- Overdriven nails in area in between top and bottom row at rim joist do not need renailed if countersunk more than 1/8" since they are not required for braced panel.
- 3" oc nailing pattern is allowable per APA report PR-N124 as shown in image below:
- Repair overdriven nails per manufacturer's spec's as shown in image below:
 - · Painting all exposed nail heads is recommended.

 - Do not overdrive nails.
 Nail head should seat **snug** to face of siding, but not be overdriven to distort the siding surface. (Figure 6A)



Revised July 2, 2021

Performance Category	Min. Nail Penetration in Framing (inches)	Panels Applied Directly to Framing					Panels Applied Over Max. 5/8-inch Gypsum Sheathing				
		Nail Size (common or	Nail Spacing at Panel Edges (inches)				Nail Size (common or	Nail Spacing at Panel Edges (inches)			
		galvanized box) ^(7,8)	6	4	3	2(4)	galvanized box) ^(7,8)	6	4	3	2(4)
5/16(5.6)	1-1/4	6d	180	270	350	450	8d	180	270	350	450
3/8(5,6)			200	300	390	510		200	300	390	510
3/8(5,6)	1-1/2	8d	220	320	410	530	10d	260	380	490(4)	640
7/16(5)			240	350	450	585		260	380	490(4)	640
19/32(5)	1-5/8	10d	340	510	665 ⁽⁴⁾	870			-	-	

- altiplied by 0.63 or 0.56, respectively. For wind load app

Sincerely,

Bradley Huxol, PE

