S LEE'S SUMMIT

1200 SE Hamblen Road | Lee's Summit, MO 64081 P: 816.969.1900 | F: 816.969.1935 backflow@cityofls.net | LSwater.net

Backflow Prevention Assembly Test Data & Maintenance Report

Dacking will cachine in Assembly		•
Trumark Homes		
Service Address 505 Carter Rd		
Location of Backflow Assembly on Property Side of House		
Side of House		
Date of Test Time AM V Supply Pressure	Air Gap (2 x Supply Diameter)	
6-23-2022 9 : 00 PM 90 LBS	Supply: <u>n/a</u> IN. Gap: <u>n/a</u> IN.	PASS FAIL
Type of Assembly Manufacturer	Model Size	Serial Number
☑ DC ☐ RP ☐ .	3/4	HF-34414
Deba (beteete)	850	
PVB* (See Bottom of Form) Height off Floor Protection From	Supply Source	New Installation
	Public Potable Water Both	✓ YES NO
n/a FT n/a IN Freezing: Yes No Flooding: Yes No	Non-Potable Water (e.g., LAKE)	
Inital Test Passed Failed	Final Test After Repair	Passed Failed
Reduced Pressure Principle Assembly:	Reduced Pressure Principle Assembly:	
RELIEF VALVE opened atPSID (2 PSID or more)	RELIEF VALVE opened atPSID (2 PSID or more)	
2nd CHECK held backpressure	2nd CHECK held backpressure	
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight	
1st CHECK held in direction of flow PSID (5 PSID or more)	그는 그리고 있다면 하나 있는데 그들은 경기를 받고 있는데 이번에 이 사람들이 되었다면 하나 되었다면 하나 되었다면 하나 되었다면 하나 나는데 하는데 하는데 하는데 하나 하나 하나 나는데 하나 없었다.	
DIFFERENCE (1st check - relief) PSID (3 PSID or more)	DIFFERENCE (1st check - relief)PSID (3 PSID or more)	
Note: Failure of any of the above items, requires repair.	Note: Failure of any of the above items, requires repair.	
Initial Test Passed Failed	Final Test After Repair	Passed Failed
Double Check Valve Assembly:	Double Check Valve Assembly:	
1st CHECK held in direction of flow 3.0 PSID (1 PSID or more)	1st CHECK held in direction of flowPSID (1 PSID or more)	
2nd CHECK held backpressure	2nd CHECK held in dissertion of flow PSID (1 PSID or more)	
2nd CHECK held in direction of flow 2.6 PSID (1 PSID or more)	2nd CHECK held in direction of flow PSID (1 PSID or more)	
NO. 2 SHUTOFF VALVE leak tight	NO. 2 SHUTOFF VALVE leak tight	
Note: Failure of any of the above items, requires repair.	Note: Failure of any of the above items, requires re	epair.
Application: Comments		
Commercial installed and tester	ed backflow working correctly	
✓ Irrigation		
Fire Line		
Fire Line By-Pass		
**Meter#		
**Meter Read		
Point of Use		
The Above Report is Certified to be True, Accurate and Complete Tested By (Print) (Signature)	Repaired by (Print) (Signature)	Date of Repair
Daniel J Coster	(Signature)	- Lie of Reput
Company	Final Test By (Print) (Signature)	Date of Final Test
Pine Valley Lawn & Landscape		
Missouri Certification Number Expiration Date	Owner or Owner's Representative	Date
34-11206 9-30-2022		
*If an existing PVB is beyond repair and needs replacement, it should	be replaced by a DC or RP to meet current State and	City regulations.

*If an existing PVB is beyond repair and needs replacement, it should be replaced by a DC or RP to meet current State and City regulations.

New PVB installations or replacements are not permitted.

**METER # and METER READ for the fire line by-pass meter on detector assemblies are required.

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.