

1200 SE Hamblen Road | Lee's Summit, MO 64081

Backflow Prevention Assembly Test Data & Maintenance Report

Backnott	revention	/ toocimory	icst bata d	Mameena	ice ireb	016
Truma	rk Homes					
Service Address 540	Carter Rd					
Location of Backflow Assemb	bly on Property	. (-
	Side	ot House				
Date of Test	Time AM 🗸	Supply Pressure	Air Gap (2 x Supply Diameter)			
6-23-2022	9 : 30 PM	90 LBS	Supply: n/a IN. Gap: I		PASS	FAIL
Type of Assembly		Manufacturer	Model	Size	Serial Number	
DC DC	□ RP	Manufacturer	Woder	3/4	HF-34380	
DCDA (Detector)		Febco	850	3/4	HF-34300	
PVB* (See Bottom of Fo						
Height off Floor	Protection From		Supply Source		New Installation	
n/a _{FT} n/a _{IN}	Freezing: Yes V No	Flooding: Yes V No	Public Potable		YES	NO
- FI THE IN			Non-Potable Water (e.g., LAKE)			
Inital Test Passed Failed			Final Test After Repair Passed Failed			
Reduced Pressure Princip	ole Assembly:		Reduced Pressure Principle Assembly:			
RELIEF VALVE opened at _	PSID (2 PSID or more)		RELIEF VALVE opened atPSID (2 PSID or more)			
2nd CHECK held backpressure			2nd CHECK held backpressure			
NO. 2 SHUTOFF VALVE lea	ak tight		NO. 2 SHUTOFF VALVE leak tight			
1st CHECK held in direction	on of flow PSID (5 PSID	or more)	1st CHECK held in direction of flow PSID (5 PSID or more)			
	ef) PSID (3 PSID or more)		DIFFERENCE (1st check - relief) PSID (3 PSID or more)			
	e above items, requires re	nair L	Note: Failure of any of the above items, requires repair.			
reote. Failure of any of th	e above items, requires re	Note: randle of any of th	ie above items, requires r	еран.		
			Final Test After Repair		Passed	Failed
Double Check Valve Assembly:			Double Check Valve Asse	embly:		
1st CHECK held in direction of flow 2.6 PSID (1 PSID or more)			1st CHECK held in direction of flowPSID (1 PSID or more)			
2nd CHECK held backpressure			2nd CHECK held backpressure			
2nd CHECK held in direction of flow 2.2 PSID (1 PSID or more)			2nd CHECK held in direction of flow PSID (1 PSID or more)			
NO. 2 SHUTOFF VALVE leak tight			NO. 2 SHUTOFF VALVE leak tight			
	e above items, requires re			ne above items, requires re	enair	Ш
Application:		Comments				
Commercial installed and tested backflow working correctly						
✓ Irrigation						
Fire Line						
Fire Line By-Pass						
**Meter#						
**Meter Read						
Point of Use						
The Above Report is Co	ertified to be True, Accu	rate and Complete				
Tested By (Print) (Signature)			Repaired by (Print)	(Signature)	Date of Repair	
Daniel J Coster						
Company			Final Test By (Print)	(Signature)	Date of Final Test	
Pine Valley Law	vn & Landscape					
Missouri Certification Number Expiration Date			Owner or Owner's Represen	tative	Date	
34-11206 9-30-2022			Date			
	B is beyond renair and nee		be replaced by a DC or RP	to meet current State and	City regulations	
			acements are not permitte		City regulations.	

**METER # and METER READ for the fire line by-pass meter on detector assemblies are required.

Missouri State Regulation 10 CSR 60-11-010(6)(E) requires testers to report results of tests and inspections to the customer and water supplier.