CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRRES20236587 Address: 1404 NE ERNEST WAY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Residential		Khanh Nguyen	Failed	Wednesday, August 14, 2024
Corrective A	ction Required:			
	 We Action Required: Misc -Under slab plumbing support must be v -Provide flashings above window trims -Provide intersystem bonding terminal b -Provide a receptacle located within 25 f -Provide a receptacle at rear of house, a within 6.5 ft of grade -Provide floodlight for illumination of th code -Provide two 1/2" through bolts at deck l -Engineer to address cracks in the found. -Support deck ledger board to wall per constrained to be a set of the set		window trims iding terminal block ated within 25 ft of the AC u ear of house, accessible fro umination of the backyard, h bolts at deck beam-post c ks in the foundation wall rd to wall per code angers athing @ 3" oc to all studs a oc grid pattern. Remove tri hers for wall anchors; heade straps not installed; wall sh ates and sill shall be shimm ive gap at bottom plates t for truss girder above gara s per truss detail	om grade and located as required per security onnections and sill plates; nail ims for full verification ; er shall extend from hall be framed per plan hed; install full height ge at both ends

equivalent nailing

-Sill plates shall be anchored within 12" of breaks and min every 6 ft -Protect wiring home runs at wall plates where within 1.25" of surface -Install stud shoe at over bored laundry stud; protect plumbing at stud and wall top plate. Provide BOCA plate at top plate. Need to move the sink out the way for 5/8" gypsum

-Strap wall top plates bored more than 50% above kitchen sink -Bath fan flexible duct cannot exceed 14 ft per UL label. Switch out the remaining length with hard duct

-Nail exterior siding per code

-Wall appliance flexible cord shall not be concealed inside wall space -Provide security blockings at exterior doors per security code

-Window glazing located within 25" of door shall be safety tempered glazing -Tie down rear sunroom girder truss to wall; nail together girder truss per truss detail

-Provide sunroom wall receptacle spacing per code

-Engineer to address attachment of sunroom IvI beams to house and bracing of exterior wall

-Bedroom shall have direct emergency escape out to outside

-Tie down north girder truss to wall; nail together girder truss per truss detail; provide 2-stud support for girder truss; **this applies to ALL girder trusses**

-Reinforce over-bored studs (>60%) at non-bearing walls with stud shoes throughout house

-Install hangers at truss connections above master closet

-Cannot drill holes through trusses.

-Nail all hangers above stair; provide joist hanger at lvl connection

-Provide min 6 ft 8 inches of headroom clearance above stair, as measured vertically from header down to stair nose-nose plane

-Protect plumbing at bottom stair landing

-Fire block basement wall space vertically at max 10 ft intervals; fb all basement wall spaces from soffit and ceiling space

-Anchor steel columns to floor; anchor basement sill plates per code -Provide engineer inspection approval for structural slab over fill; also

address broken slab at basement bathroom showing no reinforcement rebar -Protect all plumbing per code throughout house

-Provide blockings/studs at basement exterior door hinges and screw hinges to studs

-Plan shows foundation wall under stoop, instead of I beam. Provide revised plan showing I beams under stoop and garage slab support I beam at rear wall

-Brace trusses per truss detail

****DO NOT INSULATE**

Comments: