

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200

OnlinePortal at DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20235208
Address: 2911 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Khanh Nguyen	Failed	Tuesday, August 26, 2025

Corrective Action Required:

1 LOWER LEVEL

Corrective Action Required:

2 FIRST FLOOR

Corrective Action Required:

3 SECOND FLOOR Pre-rock for corridor ceiling-OK

Corrective Action Required:

4 THIRD FLOOR -Pre-rock for corridor ceiling-OK

****Check all**

- Exterior wall not rated 1-hr per plan
- Install all wall kickers per 3/S3.31 every 4 ft
- Seal penetrations of draft-stop between units
- Fc demising wall penetration at tub and shower
- Label white current carrying conductors
- Balcony framing not completed
- Provide attic access to end units

301:

302:

303:

304:

306:

305:

-Support dryer duct @ 4 ft oc

308:

307:

310:

309:

-Damaged truss at balcony beam

312:

311:

314:

316:

-Install floor-floor screw adjacent to door

313:

315:

317:

-No header above transom windows

-Install floor-floor screw adjacent to door

318:

Corrective Action Required:

5

FOURTH FLOOR

**Check all

-Framing of balcony ceiling not per plan

-Complete corridor electrical. Fc all penetrations

401:

402:

404:

403:

406:

405:

408:

407:

410:

409:

412:

413:

411:

Corrective Action Required:

6 STAIR TOWER 1

Corrective Action Required:

7 STAIR TOWER 2

Corrective Action Required:

8 STAIR TOWER 3

Corrective Action Required:

9 ELEVATOR 1

Corrective Action Required:

10 Misc

Interior and exterior sheathed shear walls:
-Lower floor, 1st, 2nd fl

Comments: