Quality Line Truss Co., LLC

34593 S 4350 RD Address 2 Adair, OK 74330 Truss:F05


Job: QU02700_RESERVE_BLDGH_REFF

Date: 06/26/25 21:08:57


Page: 1 of 1

 SPAN
 PITCH
 QTY
 OHL
 OHR
 PLYS
 SPACING
 WGT/PLY

 5-4-8
 0/12
 4
 0-0-0
 0-0-0
 1
 19.19 in
 31 lbs









All plates shown to be Eagle 20 unless otherwise noted.

Loading (psf)	General		CSI		Deflectio	n	L/	(loc)	Allowed
TCLL: 40	Bldg Code:	IBC 2018/	TC:	0.13 (1-2)	Vert TL:	0.01 in	L/999	(5-6)	L/240
TCDL: 10		TPI 1-2014	BC:	0.10 (6-7)	Vert LL:	0.01 in	L/999	(5-6)	L/360
BCLL: 0	Rep Mbr:	Yes	Web:	0.05 (1-7)	Horz TL:	0 in		5	
BCDL: 10	Lumber D.O.1	L.:100 %							

Reaction

JT	Brg Combo	Brg Width	Rqd Brg Width	Max React	Max Grav Uplift	Max MWFRS Uplift	Max C&C Uplift	Max Uplift	Max Horiz
-8	1	3.5 in	1.50 in	301 lbs	•	•	•	•	•
5	1	3.5 in	1.50 in	301 lbs	•				

Material

TC: SYP#1 4 x 2 BC: SYP#1 4 x 2 Web: SYP#1 4 x 2

Loads

1) Concurrent minimum storage attic loading has been applied in accordance with IBC 1607.1

Member Forces
Table indicates: Member ID, max CSI, max tension force, (max compression force). Only forces greater than 300lbs are shown in this table.

IC					
BC					
Web	1-7	0.055	330 lbs		
	4-6	0.055	330 lbs		

Notes

- 1) Unless noted otherwise, do not cut or alter any truss member or plate without prior approval from a Professional Engineer.
- 2) The fabrication tolerance for this floor truss is 10% (Cq = 0.90).
- 3) A creep factor of 2.00 has been applied for this truss analysis.
- 4) The "SYP" label shown in the "Material Summary" above indicates the new SPIB design values effective June 1, 2013 were used.