

Stormwater Pollution Prevention Plan Inspection Report

Project Name and Location: Blackwell

Weather: 65				
		□Clo	udy ⊠Sunny □Rain □ Snowing/ Snow cover	
Date of inspection: 9/29/25				
Inspectors Name: Jessica Ekster				
Type of Inspection: ⊠ Regular □ Rain event □ Other:				
Rain in last 24 hrs (inches): NA				
Owner/Permittee: Griffin Riley				
Current Site Condition: Active				
BMP Checklist	<u>Yes</u>	<u>No</u>	Current Construction/Active Areas:	
Inlet Barriers	<u>N</u>		Vertical & blanket detention pond	
Sediment Barriers	\boxtimes			
Construction Entrance	<u>N</u>			
Stream Crossings		<u>N</u>		
Seed/Sod/Hydroseed/Mulch/Blanket		<u>N</u>		
Sediment Basins & Discharge Locations		<u>⊠</u>		
Borrow Areas		\boxtimes		
General Site Conditions		X		
Concrete Washout	X			

<u>Problem Areas/Special Observations (Note problem areas ONLY below):</u>

BMP	Location	Observation, Effectiveness, & Corrective Actions Ordered
Silt fence	Along curb	Repair/replace silt fence along curb throughout site
Stabilize	Swale	Stabilize swale on North end as soon as possible if work is done
Stabilize	Detention Pond	Stabilize detention pond along North side- weeds are not considered vegetation
Silt fence	West side	Repair/replace silt fence down along perimeter near existing homes
Inlets	Field inlets	Need to reset/repair/replace silt fence around field inlet
Inlets	End of stub street near East side	Silt built up against inlet needs removed and silt fence in front needs reset/replacedInlets are burried

Have items noted on the last inspection been corrected? \square Yes \bowtie No (if no explain): Need to stabilize North side det. pond and swale--Weeds do not count as vegetation. Need to rewrap field inlets and curb inlets at East end of side near dirt road.

Note: Inspection comments above indicate deficiencies only. Deficiencies must be corrected within 7 days, unless otherwise noted. All other BMP's on site are considered to be in good working condition.

Signature:

Welch Silt I wheek Liveren control Lee

3003 Cantrell Rd, Harrisonville, MO 64701



BMP	Location	Observation, Effectiveness, & Corrective Actions Ordered
Silt fence	Along curbs	Repair/replace silt fence in various areas along curb
Fuel Tank	Off SE Wood Lane	Is fuel tank onsite double walled? If not, the tank needs to be removed from the site or placed in a secondary containment. An example is pictured below
Street	Various	Clean streets

Examples of fuel tanks in secondary containments.





