

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200

**OnlinePortal at DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20235207  
Address: 2931 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Khanh Nguyen	Partial	Thursday, November 13, 2025

Corrective Action Required:

1 LOWER LEVEL -Tub&shower walls -mud&taped  
-Dwelling walls and ceiling  
-Corridor

Corrective Action Required:

2 FIRST FLOOR -Tub&shower walls -mud&taped  
-Corridor ceiling nailing  
-Dwelling walls and ceiling  
-Accessible garage, wall in floor space

Corrective Action Required:

3 SECOND FLOOR -Tub&shower walls -mud&taped  
-Dwelling walls and ceiling  
-Corridor walls and ceiling  
-mechanical rooms in units fire caulking where will be covered by duct work

Corrective Action Required:

4 THIRD FLOOR -Tub&shower walls -mud&taped  
-Firestop of floor&ceiling penetrations  
-Dwelling walls and ceiling  
-mechanical rooms in units fire caulking where will be covered by duct work

Corrective Action Required:

5 FOURTH FLOOR -Tub&shower walls -mud&taped  
-Dwelling walls and ceiling

- Corridor walls and ceiling
- gypcreeet dead spaces at corridor
- mechanical rooms in units fire caulking where will be covered by duct work

Corrective Action Required:

6 STAIR TOWER 3 \*\*THIS IS REAR STAIR B\*\*  
 -Walls and ceiling

Corrective Action Required:

7 ELEVATOR 1 \*\*front side of elevator, provide lapping of GB at seams  
 \*\*inner side at elevator door, 1st layer ok

Lower floor:

- 004 dwelling side 2nd layer
- corridor side 1st layer
- stair side 2nd layer
- inner side 2nd layer
- front side 1st layer

1st floor:

- 104 dwelling side 2nd layer
- corridor side 1st layer
- stair side 2nd layer
- inner side 2nd layer
- front side 1st layer

\*\*front side, provide 1st layer at top right corner

\*\*fix corridor side 2nd layer

2nd floor:

- 207/209 dwelling side 2nd layer
- corridor side 2nd layer
- inner side 2nd layer
- front side 1st layer

3rd floor:

- 307/309 dwelling side 2nd layer
- corridor side 2nd layer
- inner side 2nd layer
- front side 1st layer

4th floor:

- 405/407 dwelling side 2nd layer
- corridor side 2nd layer
- top lid-complete
- inner side 2nd layer
- front side 1st layer

Corrective Action Required:

8 Misc

Corrective Action Required:

9 STAIR TOWER 1 \*\*THIS IS NORTH STAIR A\*\*

Lower floor:  
-stair side 2nd layer  
-outer side 1st layer

1st floor:  
-stair side 2nd layer  
-garage&storage side, 1st layer; floor space 2nd layer

2nd floor:  
-stair side 2nd layer  
-outer side 2nd layer

3rd floor:  
-stair side 2nd layer  
-outer side 2nd layer

4th floor:  
-stair side 2nd layer  
-outer side 2nd layer  
-top lid completed

Corrective Action Required:  
10 STAIR TOWER 2

**\*\*THIS IS SOUTH STAIR A\*\***

Lower floor:  
-stair side 2nd layer  
-outer side 1st layer

1st floor:  
-stair side 2nd layer  
-corridor side 2nd layer  
-dwelling side 2nd layer  
-garage and storage side 1st layer; floor space 2nd layer

2nd floor:  
-stair side 2nd layer  
-outer side 2nd layer

3rd floor:  
-stair side 2nd layer  
-outer side 2nd layer

4th floor:  
-stair side 2nd layer  
-outer side 2nd layer  
-top lid completed

**Comments:**