

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**OnlinePortal at DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20235208  
Address: 2911 SE SHENANDOAH DR, LEES SUMMIT, MO 64063

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Khanh Nguyen	Partial	Tuesday, December 02, 2025

Corrective Action Required:

1	LOWER LEVEL	-Tub&shower walls screw pattern oK -Corridor ceiling  **cut off protruding wood at corridor ceiling and cover with GB **Fc gap at top of shower wall (unit 008 and unit near middle corridor)
---	-------------	---

Corrective Action Required:

2	FIRST FLOOR	-Tub&shower walls-mud and tape OK -Garage walls in ceiling space -Corridor ceiling -Dwelling walls and ceiling
---	-------------	---

Corrective Action Required:

3	SECOND FLOOR	-Tub&shower walls -mud&taped -screw pattern corridor ceiling -Dwelling walls and ceiling -Corridor walls and ceiling
---	--------------	---

Corrective Action Required:

4	THIRD FLOOR	-Tub&shower walls-mud&taped -Kitchen/corridor walls -Corridor ceiling -Dwelling walls and ceiling -Corridor walls and ceiling
---	-------------	---

-Gypcrete ok

\*\*repair GB at unit 305 shower  
-305 has been fire blocked it shower wall

Corrective Action Required:  
5 STAIR TOWER 1

**\*\*THIS IS NORTH STAIR A\*\***

Lower floor:  
-stair side 2nd layer

1st floor:  
-stair side 2nd layer  
-outer side 1st layer

2nd floor:  
-stair side 2nd layer  
-dwelling and corridor side, 2nd layer

3rd floor:  
-stair side 2nd layer  
-dwelling and corridor side, 2nd layer

4th floor:  
-dwelling side 2nd layer  
-corridor side, 1st layer

Corrective Action Required:  
6 STAIR TOWER 2

**\*\*THIS IS SOUTH STAIR A\*\***

Lower floor:  
-stair side 2nd layer

1st floor:  
-stair side 2nd layer  
-outer side 1st layer

2nd floor:  
-stair side 2nd layer  
-dwelling and corridor side, 2nd layer

3rd floor:  
-stair side 2nd layer  
-dwelling and corridor side, 2nd layer

4th floor:  
-dwelling side 2nd layer  
-corridor side, 2nd layer

Corrective Action Required:  
7 STAIR TOWER 3

**\*\*THIS IS REAR STAIR B\*\***

Lower floor:

Corrective Action Required:  
8 ELEVATOR 1

-elevator/stair wall-stair side 2nd layer

Lower level:

- inner side 2nd layer
- dwelling side 2nd layer
- corridor side 1st layer
- stair side 2nd layer

1st floor:

- inner side 2nd layer
- dwelling side 2nd layer
- corridor side 1st layer
- stair side 2nd layer

2nd floor:

- inner side 2nd layer
- dwelling side 2nd layer
- corridor side 2nd layer
- front side 1st layer

3rd floor:

- inner side 2nd layer
- dwelling side 2nd layer
- corridor side 2nd layer

\*\*2nd layer already mud&taped; first layer broken off at opening

4th floor:

- inner side, 2nd layer
- dwelling side 2nd layer
- top lid, 3rd layer

\*\*corridor side 2nd layer installed, but 1st layer not inspected

Corrective Action Required:  
9 FOURTH FLOOR

- Tub&shower walls-screw OK
- Kitchen/corridor wall-screw OK
- Dwelling walls and ceiling
- Corridor walls and ceiling
- Gypcrete ok

Informational:  
10 Misc

Fireguard sheathing installed at exterior wall facing building 3, as called for in CMR-OK

**Comments:**