

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

Inspection Summary

Permit #: PRRES20132088, Building Permit - Residential Address: 1316 NE ERNEST WAY, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

All Rough Inspection - Residential Khanh Nguyen Failed Wednesday, January 15, 2014 Corrective Action Required -	Inspection:	Inspector:	Outcome:	Date:
1 MISC -NAIL GARAGE PORTAL BRACE WALL SHEATHING PER CODI -NAIL CORNER STUDS AT REAR DINING WALL -BLOCK THE DECK DOOR STUDS TO CORNERS AT STRIKE PLATE HEIGHT -FIREBLOCKING: REAR DUCT/PLUMBING SPACE (FB GAP); FI VERTICAL SPACES AT KITCHEN/GARAGE WALL FROM HORIZONTAL SPACE; FB GARAGE DUCT/PLUMBING SPACE FROM ROOF AND SOFFIT -INSTALL BOOT FLASHING FOR 3" VENT -INSTALL BOCA PLATE AT BATH/LAUNDRY WALL TOP PLATE **OK TO INSULATE. NO ROCK **NO ACCESS CODE TO GET INSIDE. 2ND RE-INSPECTION. 3 RE-INSPECTION WILL RESULT IN AN ISSUANCE OF REINSPECTION	Inspection -	Khanh Nguyen	Failed	Wednesday, January 15, 2014
	•	-NAIL -NAIL -BLOO PLAT -FIRE VERT HORI FROM -INST -INST -INST **OK **NO	CORNER STUDS AT F CK THE DECK DOOR S E HEIGHT BLOCKING: REAR DUC TCAL SPACES AT KITC ZONTAL SPACE; FB G N ROOF AND SOFFIT ALL BOOT FLASHING ALL BOCA PLATE AT E TO INSULATE. NO ROO ACCESS CODE TO GE	REAR DINING WALL STUDS TO CORNERS AT STRIKE CT/PLUMBING SPACE (FB GAP); FB CHEN/GARAGE WALL FROM ARAGE DUCT/PLUMBING SPACE FOR 3" VENT SATH/LAUNDRY WALL TOP PLATE CK CT INSIDE. 2ND RE-INSPECTION. 3RD
			ISPECTION WILL RESU	JET IN AN ISSUANCE OF REINSPEC

Comments: