PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20140176, Building Permit - Commercial Address: 880 NW BLUE PKWY, Unit:C, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Above Ceiling Inspection		John Borns	Not Ready	Monday, May 05, 2014
Corrective	e Action Require	ed		
1	MISC		TEMPORARY ELECTRICAL WIR SPACE.	ING NOT REMOVED FROM ABOVE CEILING
Corrective	e Action Require	ed		
2 MISC		SEVERAL ELECTRICAL JUNCTION BOXES NOT CLOSED.		
	e Action Require	ed		
3	MISC		ROUTE HIGH IN INTERSTITIAL LAID LOOSE ON CEILING GRID	URING OF LOW VOLTAGE ELECTRICAL CABLE: SPACE >= 18" ABOVE CEILING GRID; NOT TO BE ; DROP TO TERMINATIONS WHERE LOCATED. NOT FROM OTHER M/E/P SYSTEMS.
Corrective	e Action Require	ed		
4 MISC		NEC 334-10 SECURING / SUPPORT OF MC ELECTRICAL CABLE: SECURE WITHIN 12" OF BOXES AND SUPPORT AT 6' MAX INTERVALS THEREAFTER.		
Gas Service Inspection - John Borns Commercial			Partial	Monday, May 05, 2014
Partial Co	rrection			
1	MISC		GAS PIPING PRESSURE TEST H RELEASE GAS SERVICE.	IELD STEADY AT >= 10 PSI FOR >=10 MIN.
Corrective	e Action Require	ed		
2	2 MISC		ADDRESS IDENTIFICATION OF GAS SERVICE ENTRY: WHERE TWO OR MORE SERVICES ARE GROUPED LOOSE-HANG ADDRESS-STAMPED MEDALLION ON LOAD SIDE PIPE.	
Gas Piping Inspection - John Borns Commercial		Failed	Monday, May 05, 2014	

 Corrective Action Required
 1
 MISC
 ROOFTOP GAS PIPING SUPPORT BLOCKS NOT PER DRAWING REQUIREMENT.

 Corrective Action Required
 2
 MISC
 IFGC 404.8: METALLIC PIPING EXPOSED TO WEATHER MUST BE

 DEFENSION
 DEFENSION FUNCTION OF DY OTHER ADDROVED MEANS

PERMANENTLY PROTECTED WITH PAINT OR BY OTHER APPROVED MEANS. SEE GAS PIPING AT METER AND ROOFTOP.

Comments: