

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial
Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Partial	Wednesday, April 22, 2015

Corrective Action Required

1	FIRST FLOOR	UNIT "D" INSTALL DUCT AND DAMPER FURNACE ROOM CEILING NEED ROCK AND TRAP LOWERED OR FLOOR CEILING ASSEMBLY LOWERED
---	-------------	---

Partial Correction

2	SECOND FLOOR	OK TO COVER WALLS AND CEILINGS AT 2ND FLOOR EXCEPT
---	--------------	--

Corrective Action Required

3	Misc 1
---	--------

Corrective Action Required

4	THIRD FLOOR	OK TO ROCK UNITS AND WALLS TUB TRAPS INSPECTED
---	-------------	---

Corrective Action Required

5	LOWER LEVEL	LOWER GARAGE LEVEL- GARAGE CEILING OK TO INSULATE AND INSTALL RC CHANNEL. WALL HAVE NOT BEEN INSPECTED, NOR THE CORRIDOR WALLS.
6	FOURTH FLOOR	OK to rock ceiling only for mechanical drops and soffits

Corrective Action Required

Rated Assembly Inspection

Mark Harding	Partial	Wednesday, April 22, 2015
--------------	---------	---------------------------

Corrective Action Required

1	FIRST FLOOR	ROOMS- ALL EXEPT 1103,1106,1112 CORRIDOR- CAULK EDGES- USED FOAM,
---	-------------	--

Corrective Action Required
2 SECOND FLOOR

CORRIDOR-
CAULK 2ND LAYER- USED FOAM FOR GAPS , PROVIDE LISTING OR CUT BACK
ROCK AND FIT TIGHT

Corrective Action Required
3 THIRD FLOOR

CORRIDOR-2ND LAYER OK

Corrective Action Required
4 FOURTH FLOOR

CORRIDOR
1,2, OK CAULK GAPS ON 2ND

ROOMS - CEILING OF 4TH FLOOR OK EXECPT 1406 GAP IN ROCK

Corrective Action Required
5 LOWER LEVEL

RATED CEILING - OK TO ROCK 2ND LAYER OVER WHERE SPRINKLER HEAD
WAS REMOVED.
SEAL GAP AROUND HEAD FAR WEST CLOSET AREA.
BOTH LAYERS

Corrective Action Required
6 B705 FIRE WALLS

1ST LAYER CORRIDOR AND STAIR WALL
OK 1-4 ON EAST STAIR WAY

4TH FLOOR WEST STAIRS AT LADDER TO ROOF NEEDS INSPECTED.

ELEVATOR 2ND LAYER OK,
2ND LAYER OF CEILING ELEVATOR OK

Comments: