

## Inspection Summary

Permit #: PRCOM20141079, Building Permit - Commercial

Address: 3361 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>In-wall Inspection</b>	Mark Harding	Partial	Friday, May 01, 2015

**Corrective Action Required**

1	FIRST FLOOR	1-4TH FLOOR PREROCK SHOWERS FAILED, SUPPORT TRUSS AT CUT PLATES, CAULK ALL PENETRATIONS TURN OUT CLEAN OUTS AT 1ST/GROUND FLOOR. TOILET WATER LINE PIPING TURNED IN WALL. RECALL WHEN READY
---	-------------	--

**Corrective Action Required**

2 SECOND FLOOR

**Corrective Action Required**

3	THIRD FLOOR	PRE ROCK AT SHOWER WALLS OK TO ROCK
---	-------------	-------------------------------------

**Corrective Action Required**

4	FIRST FLOOR	PRE ROCK AT SHOWER WALLS OK TO ROCK
---	-------------	-------------------------------------

**Comments:**