

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141078, Building Permit - Commercial
Address: 3351 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

| | | | |
|----------------------------------|--------------|----------|----------------------|
| Inspection: | Inspector: | Outcome: | Date: |
| Rated Assembly Inspection | Mark Harding | Partial | Friday, May 01, 2015 |

Corrective Action Required

| | | |
|---|-------------|-----------|
| 1 | FIRST FLOOR | 1ST LAYER |
|---|-------------|-----------|

Corrective Action Required

| | | |
|---|--------------|---|
| 2 | SECOND FLOOR | CORRIDOR-1ST OK 2ND LAYER AT 2HR WALLS EXTERIOR SIDE IT ROOM FAILED |
|---|--------------|---|

Corrective Action Required

| | | |
|---|-------------|--|
| 3 | THIRD FLOOR | 2ND LAYER AT 2HR WALLS EXTERIOR SIDE SOUTH STAIRS- 2ND LAYER OK |
|---|-------------|--|

Corrective Action Required

| | | |
|---|--------------|---|
| 4 | FOURTH FLOOR | CORRIDOR 1,2, OK CAULK GAPS ON 2ND ROOMS - 1ST LAYER STAIR WALLS ABOVE 4TH FLOOR -1ST LAYER STAIRS CEILING - - |
|---|--------------|---|

Corrective Action Required

| | | |
|---|-------------|---|
| 5 | LOWER LEVEL | RATED CEILING - 2ND LAYER OK , EXCEPT OUTSIDE IT ROOM. EAST END OF CORRIDOR NEEDS SHEETROCKED WHEN PIPES ARE DROPPED FROM CEILING. |
|---|-------------|---|

ALCOVES IN CORRIDOR NEEDS 1ST LAYER
(INSTALLED CHANNEL ON CEILINGS NEEDS REMOVED)

Corrective Action Required

6

Misc 1

1ST FLOOR CORRIDOR OK, "D" UNIT OK
2ND FLOOR IT ROOM 6" DUCT TO FLOOR SPACE NEEDS FIXED
2ND FLOOR "D" UNIT 3RD FLOOR CAULK PLUMBING LINES TO FLOOR SPACE
3RD FLOOR OK
4TH DRYER VENTS ok
BSMT - 1ST OF 2HR WALLS
3RD OF 4 AT EAST STAIR TOWER
IT ROOMS 2ND

Comments: