

PLANNING AND CODES ADMINISTRATION DEPARTMENT  
220 SE GREEN STREET  
LEE'S SUMMIT, MO 64063  
(816) 969-1200 FAX (816) 969-1201

## Inspection Summary

---

Permit #: PRCOM20141079, Building Permit - Commercial  
Address: 3361 SW KESSLER DR, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

---

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Mark Harding	Failed	Thursday, June 18, 2015
Corrective Action Required 1 SECOND FLOOR		2ND FLOOR UNITS;	
Corrective Action Required 2 THIRD FLOOR			
Corrective Action Required 3 FOURTH FLOOR		1ST LAYER 4TH FLOOR CEILING; 2ND LAYER 4TH FLOOR NEED TO CUT OUT AND CAULK BLOTH LAYERS OF PENETRATIONS	
Corrective Action Required 4 FIRST FLOOR		2ND FLOOR UNITS; 2ND LAYER - 2HR CONDITIONS - 2ND FLOOR; 2ND LAYER CEILING - 4TH FLOOR; 1ST LAYER 2HR CONDITIONS - 3RD & 4TH FLOORS;	
Corrective Action Required 5 Misc 1		2212 SCREW WALL 2210 SCREW 3RD FLOOR UNITS 3207 BACK SIDE OF ELEVATOR NEED 2ND LAYER , KITCHEN SIDE NEEDS 1ST LAYER INSPECTED -4TH FLOOR STAIR SOUTH STAIR RE-HANG 4TH LAYER GAPS AND INCORRECT CEILING. NORTH STAIR 4TH OK CEILING	

**All Rough Inspection - Commercial** - Mark Harding Failed Thursday, June 18, 2015

Corrective Action Required  
1 FIRST FLOOR UNITS-ONLY  
6/17;6/18  
-CAULK ROOF DRAINS AT PLATE LINE  
-HVAC CORRIDOR , 2LAYERS OF ROCK COMPROMISED FOR HVAC THROUGH

WALL  
-CAULK ROOF DRAIN G7  
G8- CLEAN OUT  
G8 ANCOR BOLTS

Corrective Action Required  
2 SECOND FLOOR  
Corrective Action Required  
3 THIRD FLOOR  
Corrective Action Required  
4 FOURTH FLOOR

COMPLETE

COMPLETE

HVAC- DROPS 4TH FLOOR INSPECTION

**Comments:**