

PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141076, Building Permit - Commercial
Address: 3331 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Mark Harding	Failed	Friday, June 19, 2015

Corrective Action Required

1	FRAMING/STRUCTURE	OK TO ROCK THE FOLLOWING- ELECATOR SHAFT 1-3
---	-------------------	---

WEST GARAGE EVE OK TO COVER
EAST 1ST FLOOR PATIOS OK

Corrective Action Required

2	FIRST FLOOR	1ST FLOOR UNIT SIDE ONLY- 3103- 24" TRUSS SPACING, AC LINE IN WRONG 3100- ROCK ARCH, GARAGE SIDE- *RISER ROOM STUDS DRILLED FOR WATER LINE *ANCOR BOLTS *SWITHC BOX FOR LIGHT IN RISER ROOM *CORRIDOR -PLUMBING CUT IN WALL *G13-JOIST HANGER NAILS, CLEAN OUTS *S8- HOLD DOWN, NORTH WALL ANCORS NUTS, CLEANOUT 3" *G6-CLEAN OUT *G5-SUPPORT PLUMBING, PLATE BOLT N WALL *G4-PLUMBING CUT STUDS REPLACE, CAULK HOOLES, PLATEA, CLEAN OUTS *JANITOR CLOSET, CUT JOSIT FOR DWV *S3-SUPPORT DWV (HCEK ALL GARAGE SIDE) SUPPORT FEEDERS GARAEG SIDE ALL CORRIDOR- INSTAL LOW VOLTAGE FIRELINE HVAC O DRY VENT STRAP INSTALL 4 NAILS.
---	-------------	--

Corrective Action Required

3	SECOND FLOOR	3200 ELECTRICAL, WATER LINE CUT, HVAC COMPELTE LAUNDRY N.W. UNIT. WATER LINES.
---	--------------	---

Corrective Action Required
4 THIRD FLOOR

3301-BROKEN TRUSS KITCHEN ISLAND
3302-ELECTRICAL TO PORCH CUT STUDS, BROKEN FLOOR TRUSS OVER ENTRY.
INSTALL CORRIDOR ELECTRICAL 3RD FLOOR
3303-TRUSS CENTER LIVING ROOM BROKEN, TRUSS REPAIR HVAC THROUGH.
3304- PLUMB OVER ISLAND SUPPORT NEED FALL
3310-CUT STUD PORCH LIGHTS
3312-FRAME , ROCK, CAULK FIRELINE,-

Corrective Action Required
5 FOURTH FLOOR

DRYER VENTS , COMPLETE
3400 DRYER VENT SCREW
LINE SETS, WIRE BATH FANS CALUK ALL ROOF DRAINS, 3406 CAULK PLMB
3410 PUDDY
3412 ROCK FIRE LINE PUDY
INCOMPLETE INSPECITON NUMEROUS ITEMS RECALL

In-wall Inspection

Mark Harding

Partial

Friday, June 19, 2015

Corrective Action Required
1 FIRST FLOOR

PRE-ROCK- TUB SHOWER WALLS
OK

Corrective Action Required
2 SECOND FLOOR

PRE-ROCK- TUB SHOWER WALLS
OK

Corrective Action Required
3 THIRD FLOOR

PRE-ROCK- TUB SHOWER WALLS
OK

Corrective Action Required
4 FOURTH FLOOR

2ND LAYERS NOT READY 6/19 ALL FLOORS
1ST LAYER 4TH FLOOR

Comments: