PLANNING AND CODES ADMINISTRATION DEPARTMENT 220 SE GREEN STREET LEE'S SUMMIT, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #: PRCOM20141079, Building Permit - Commercial Address: 3361 SW KESSLER DR, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Friday, June 26, 2015
Corrective Action Require 1 SECOND FLOO Corrective Action Require 2 THIRD FLOOR	R 2ND	FLOOR UNITS; S	
Corrective Action Require 3 FOURTH FLOO	R 1ST L 2ND PENE 4-4TI	AYER 4TH FLOOR CEILING LAYER 4TH FLOOR NEED T TRATIONS H LAYER STAIR CEILING OI & TRACK STAIRS	O CUT OUT AND CAULK BLOTH LAYERS OF
Corrective Action Require 4 FIRST FLOOR	2ND CEILI 1ST F	NG - 4TH FLOOR; 1ST LAY	R - 2HR CONDITIONS - 2ND FLOOR; 2ND LAYER ER 2HR CONDITIONS - 3RD & 4TH FLOORS; NEED 2 LAYERS UNDER TRUNK LINE AT INDER OF HALL.
Corrective Action Require 5 Misc 1	3RD 3207 KITCI -4TH CORF SPRII 1ST L	FLOOR UNITS BACK SIDE OF ELEVATOR HEN SIDE NEEDS 1ST LAYE LAYER STAIR CEILING OK RIDOR WALLS- NEED TO II NKLER LINES ALL CORIDOI AYER 2HR WALLS OK UNI valls 2nd layer	R INSPECTED NSPECT DAMAGED ROCK FROM MOVING RS-

4th layer secondary landing rated wall elevator 2nd layers

Above Ceiling	Mark Harding	Failed	Friday, June 26, 2015
Inspection			

Corrective Action Required

1 THE FOLLOWING AREAS 3RD FLOOR CORRIDOR CEILINGONLY OK TO ROCK ARE APPROVED

above ceiling failed 4 floor in d 1 units

Comments: