

**PLANNING AND CODES ADMINISTRATION DEPARTMENT
220 SE GREEN STREET
LEE'S SUMMIT, MO 64063
(816) 969-1200 FAX (816) 969-1201**

Inspection Summary

Permit #:PRCOM20161058, Building Permit - Commercial
Address: 1200 SE HAMBLER RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Underground Electrical Inspection - Commercial	John Borns	Partial	Friday, February 10, 2017

Partial Correction

1	THE FOLLOWING AREAS ARE APPROVED	-PRIMARY CONDUITS FROM TRANSFORMER PAD TO BUILDING APPROVED -NORTH PARKING LIGHTING APPROVED -SOUTH PARKING LIGHTING APPROVED -WEST PARKING LIGHTING APPROVED -DUCT BANK FROM HARDENED ROOM TO WEST LOCATION APPROVED
---	----------------------------------	---

Partial Correction

2	THE FOLLOWING AREAS ARE APPROVED	NO ISSUES FOUND ON TRENCHED PVC ELECTRICAL CONDUIT: FROM GENERATOR LOCATION: ONE 1" N/NE TO L.P. AT N EDGE OF DETENTION POND; ONE 2" + THREE 1" NE TO J.B. @ GATE CONTROLLER; FIVE 1" NW TO FUEL PUMP LOCATION
---	----------------------------------	--

Partial Correction

3	Misc 1	OK TO POUR WHEN READY LIGHT POLE BASES AT FOLLOWING LOCATIONS NUMBERED ON SITE PLAN IN PERMIT PRINT SET: #5;
---	--------	---

Underground Plumbing Inspection - Commercial	John Borns	Partial	Friday, February 10, 2017
---	------------	---------	---------------------------

Partial Correction

1	Misc 1	CONDUITS FOR PARKING LIGHTS: SOUTH AND NORTH BORDER LIGHTS APPROVED
---	--------	--

Partial Correction

2 Misc 1 EXCEPT FOR VENT PIPING YET TO BE INSTALLED OK TO COVER BOTH OIL/WATER SEPARATORS SET IN PLACE AND PIPED

Underground Electrical Inspection - Commercial John Borns Failed Friday, February 10, 2017

Partial Correction

1 THE FOLLOWING AREAS ARE APPROVED
-PRIMARY CONDUITS FROM TRANSFORMER PAD TO BUILDING APPROVED
-NORTH PARKING LIGHTING APPROVED
-SOUTH PARKING LIGHTING APPROVED
-WEST PARKING LIGHTING APPROVED
-DUCT BANK FROM HARDENED ROOM TO WEST LOCATION APPROVED

Partial Correction

2 THE FOLLOWING AREAS ARE APPROVED
NO ISSUES FOUND ON TRENCHED PVC ELECTRICAL CONDUIT: FROM GENERATOR LOCATION: ONE 1" N/NE TO L.P. AT N EDGE OF DETENTION POND; ONE 2" + THREE 1' NE TO J.B. @ GATE CONTROLLER; FIVE 1" NW TO FUEL PUMP LOCATION

Corrective Action Required

3 Misc 1 LIGHT POLE BASE RE BAR CAGES MUST BE SUSPENDED TO PROVIDE MINIMUM 3" CLEARANCE AT BOTTOM OF HOLE

Underground Plumbing Inspection - Commercial Mike Copeland Partial Friday, February 10, 2017

Partial Correction

1 Misc 1 CONDUITS FOR PARKING LIGHTS:
SOUTH AND NORTH BORDER LIGHTS APPROVED

Partial Correction

2 Misc 1 OK TO COVER BOTH OIL/WATER SEPARATORS SET IN PLACE AND PIPED. VENT PIPE TO BUILDING AT EAST UNIT; 19' OF 4" PIPE AT WEST UNIT;

Comments: