

PUBLIC WORKS ENGINEERING DIVISION

Inspection Summary

Permit #: PRPWFC20172147, Public Works Infrastructure Permit - Commercial
B&J Peerless Addition
Address: 2301 NE INDEPENDENCE AVE, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Site Visit	John DiMauro	Partial	Monday, September 18, 2017

Informational

1 John DiMauro 07/24/2017 3:36 PM
No activity today.

Informational

2 John DiMauro 07/25/2017 11:32 AM
Crew on site starting the demo of the existing concrete areas to be reconstructed.

Informational

3 John DiMauro 07/27/2017 3:44 PM
Trench and grading construction.

Informational

4 John DiMauro 07/28/2017 10:23 AM
Crews on site working on the building construction.

Informational

5 John DiMauro 07/31/2017 3:40 PM
Crews on site working on the building construction.

Informational

6 John DiMauro 08/01/2017 2:04 PM
Crews on site working on the building construction.

Informational

7 John DiMauro 08/02/2017 2:53 PM
Crews are on site installing the storm pipe.

Informational

8 John DiMauro 08/03/2017 3:03 PM
Crews working on storm pipe.

Informational

9 John DiMauro 08/07/2017 3:35 PM
Crews on site working on the building construction.

Informational

10 John DiMauro 08/08/2017 3:23 PM
Crews on site working on the building construction.

Informational

11 John DiMauro 08/09/2017 3:45 PM
Crews on site working on the building construction.

Informational

12 John DiMauro 08/22/2017 10:30 AM
No activity.

Informational

13 John DiMauro 08/28/2017 10:26 AM
No activity.

DEI-Erosion Sediment Control John DiMauro Partial
(ESC) Inspection

Monday,
September
18, 2017

Informational

1 John DiMauro 07/25/2017 11:31 AM
The silt fence is installed and intact according to the plans.

Informational

2 John DiMauro 07/27/2017 3:42 PM
The sediment fence is intact. No debris washing out.

Informational

3 John DiMauro 08/07/2017 3:36 PM
The sediment fence is intact. No debris washing out.

Informational

4 John DiMauro 08/08/2017 3:24 PM
The sediment fence is intact. No debris washing out.

Corrective Action Required

5 John DiMauro 08/22/2017 10:28 AM
There are problems with the erosion control devices on your site. There is a section of the sediment fence that has failed due to the rain event. This fence needs to be fixed and corrected.

Informational

6 John DiMauro 09/11/2017 3:46 PM
Erosion control devices are intact.

Informational

7 John DiMauro 09/18/2017 3:41 PM
Erosion control devices are intact.

Comments:
