

Inspection Summary

Permit #: PRRES20171770, Building Permit - Residential
Address: 1801 SW BLACKSTONE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Dale Carter	Failed	Thursday, September 28, 2017

Corrective Action Required

- | | | |
|---|------|--|
| 1 | Misc | 5. BSMT: Shim full-width of steel beams.
8. 1st FLR: Firestopping along all of rear garage wall.
9. 1st FLR: Firestop under tub over garage.
13. 2nd FLR: Block joists at load-bearing walls, per plans.
16. 2nd FLR: BOCA plate at BR#3.
17. 2nd FLR: Missing hangers at ceiling coffer over BR#3.
*Hangers now in place, but not nailed.
18. 2nd FLR: 3 studs under both ends of LVL at BR#4.
22. 2nd FLR: Slope DWV in attic. |
|---|------|--|

Comments: