

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRPWFR20171746, Public Works Infrastructure Permit - Residential  
Manor at Stoney Creek 2nd - street, storm, sewer and water

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection	Brice Lawson	Failed	Monday, October 09, 2017

Corrective Action Required

1 There are problems with the erosion control devices on your site.

Brice Lawson 10/09/2017 12:06 PM

The silt fence located north of the temp. sediment trap has been damaged and needs to be repaired.

Sections of the silt fence along the north perimeter are laying down or silt is built of to the top of the silt fence making it ineffective.

Perform maintenance and repair these sections of silt fence.

Comments: