Development Services Department

220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Inspection Summary

Permit #:PRCOM20161765, Building Permit - Commercial Address: 801 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly John Borns Partial Friday, October 13, 2017

Inspection

Partial Correction

1 Misc OK TO COVER RATED ASSEMBLIES AT STAIRWELLS:

SOUTH STAIRWELL:

FIRST FLOOR 1ST & 2ND LAYERS 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS;

SECOND FLOOR: 1ST LAYER 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS; 2ND LAYER 5/8" TYPE X; 2ND LAYER PRE-ROCK AT TRUSS-JOIST BAYS;

THIRD FLOOR: 1ST LAYER 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS; [2ND LAYER 5/8" TYPE X PRE-ROCK AT TRUSS-JOIST BAYS;

NORTH STAIRWELL:

FIRST FLOOR 1ST & 2ND LAYERS 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS;

SECOND FLOOR: 1ST LAYER 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS; 2ND LAYER 5/8" TYPE X; [2ND LAYER PRE-ROCK AT TRUSS-JOIST BAYS;

THIRD FLOOR: 1ST LAYER 5/8" TYPE X MOLD-TOUGH GWB INCLUDING PRE-ROCK AT TRUSS-JOIST BAYS; [2ND LAYER 5/8" TYPE X GWB PRE-ROCK AT TRUSS-JOIST BAYS;

Partial Correction

2 Misc OK TO COVER RATED ASSEMBLIES PRE-ROCK AT ELEVATOR

SHAFT:

FIRST FLOOR: 1ST & 2ND LAYERS PRE-ROCK AT TRUSS-JOIST BAYS;

SECOND FLOOR: 1ST LAYER PRE-ROCK AT TRUSS-JOIST BAYS; 2ND

LAYER 5/8" TYPE X PRE-ROCK AT TRUSS-JOIST BAYS;

THIRD FLOOR: 1ST LAYER PRE-ROCK AT TRUSS-JOIST BAYS;

Partial Correction

3 Misc OK TO TAPE, MUD, AND FIRESTOP 5/8" TYPE X PRE-ROCK GWB

AT TUB/SHOWER WALLS AT:

4TH FLOOR 3RD FLOOR 2ND FLOOR

Partial Correction

4 Misc OK TO COVER WHEN READY 5/8" TYPE X GWB AT **CEILINGS AND**

WALLS AT: 1ST FLOOR IT ROOM 1ST LAYER:

Rough Framing John Borns Partial Friday, October 13, 2017

Inspection -Commercial

Partial Correction

4 Misc OK TO COVER WHEN READY TWO SHEAR WALLS AT BACKSIDE

OF STAIRWELLS AT 1ST FLOOR;

Comments: