

**PUBLIC WORKS ENGINEERING DIVISION**

## Inspection Summary

Permit #: PRSUBD20180158, Development - Subdivision  
Park Ridge 6th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

Inspection:	Inspector:	Outcome:	Date:
DEI-Erosion Sediment Control (ESC) Inspection Informational	Jeremy Young	Partial	Wednesday, May 30, 2018
1	Jeremy Young 04/09/2018 9:28 AM All ESC devices are intact and seem to be functioning properly. I have asked the crew to add gutter protection to the 2 inlets on Bluestone.		
Informational			
2	Jeremy Young 04/19/2018 3:38 PM All ESC devices appear to be intact and working properly. All silt fences and mulch is intact.		
Informational			
3	Jeremy Young 04/26/2018 3:41 PM Please add some mulch to the east side of the road on Bluestone. There was some utility work done and the ESC needs to be put back.		
Informational			
4	Jeremy Young 05/03/2018 2:00 PM All ESC devices are present and working properly. Please add some mulch to the east side of Bluestone Dr.		
Informational			
5	There are problems with the erosion control devices on your site.		

The silt fence on the north side of the property and west of Seneca Terr is down in several places. Please staple back into place.

The mulch berms are intact and working properly.

Comments: