een inspecte	· · · · · · · · · · · · · · · · · · ·	ults noted below. Please ca	all for re-inspection
=	· · · · · · · · · · · · · · · · · · ·		all for re-inspection
=	· · · · · · · · · · · · · · · · · · ·		all for re-inspection
This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.			
1:	Inspector:	Outcome:	Date:
Inspection	John Jackson	Partial	Tuesday, November 20, 2018
ractor installe	d approximately 60% of	curh on newly constructed	l roads All curbs were
		·	rodds. All carbs were
nued installat nd cement co	ion of curbs Monday 11	/19/18 & blanketed curbs a	as section 502.4.1
i 4	keted due to t ractor installe inued installat	b Inspection John Jackson ractor installed approximately 60% of keted due to the forecasting of overnicator installed 60% of curbs on 11/16 inued installation of curbs Monday 11 and cement concrete base pavement 6	b Inspection John Jackson Partial ractor installed approximately 60% of curb on newly constructed keted due to the forecasting of overnite freezing temperatures. ractor installed 60% of curbs on 11/16/18 Friday & blanketed curbs inued installation of curbs Monday 11/19/18 & blanketed curbs and cement concrete base pavement Cold Weather Concrete. John