

Inspection Summary

Permit #: PRSUBD20180158, Development - Subdivision
Park Ridge 6th Plat

Address:

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection Item:

| Inspection: | Inspector: | Outcome: | Date: |
|--|---------------|----------|-------------------------|
| DE - Erosion Sediment Control (ESC) Inspection | Steve Robbins | Failed | Wednesday, May 08, 2019 |

Corrective Action Required

| | | |
|---|---|-------------------------------------|
| 1 | There are problems with the erosion control devices on your site. Please take a look at the silt on the road and the silt in the gutter buddies throughout the 6 th plat. | Steve Robbins 05/08/2019 8:36 AM |
|---|---|-------------------------------------|

Comments: