Inspection Summary				
	.876, Public Works Infrastruc d Plat Street/Storm/MDP/ES			
•	ected and the inspection resuns have been completed. Do		•	
Inspection Item: Inspection:	Inspector:	Outcome:	Date:	
DE - Storm - Swales	Steve Robbins	Partial	Wednesday, July 24, 2019	
Corrective Action Required	d			
Corrective Action Requi				
pl. which back completed bu instead of a 4 after the rainf	r cut in a swale starting from s up to addresses 1709 to 16 t the 3 field inlets still need to inlet structure. The swale wat all we had over the weekend the this week and after they watation.	37 on sw napa valley dr. To be grouted in to make the scut in last friday and it and the contractor is planning.	he swale has been nem a 2 inlet structure ppeared to be working g on grouting in the	
Comments:				

220 SE Green Street   Lee's Summit, MO 64063   816.969.1200   816.969.1201 Fax   cityofLS.net/Development  Page 2		