nspection Item: Inspection: Water Service Inspection - Steve Robbins Commercial Informational	MARTIN CITY PIZZA & TAPS Address: 354 SW BLUE PKWY, LEES SUMMIT, MO 64063 This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved. Inspection Item: Inspection: Inspector: Outcome: Date: Water Service Inspection - Steve Robbins Passed Monday, Septembe 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line are was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.
nspection Item: Inspection: Inspector: Outcome: Date: Water Service Inspection - Steve Robbins Passed Monday, Commercial September 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line a was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.	Inspection Item: Inspection: Inspector: Outcome: Date: Water Service Inspection - Steve Robbins Commercial Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line are was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.
Mater Service Inspection - Steve Robbins Passed Monday, Commercial September 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line a was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.	Water Service Inspection - Steve Robbins Passed Monday, Commercial September 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line are was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.
September 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line a was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.	September 30, 2019 Informational The new 4" fire sprinkler service line was connected to the existing 6" private fire line are was ran to the building . 2 thrust blocks were poured and rock was installed and then backfilled.