NW ORCHARD S	., Development - Subdivis T, LEES SUMMIT, MO 640				
as been inspecte	T, LEES SUMMIT, MO 640				
•		Address: 6 NW ORCHARD ST, LEES SUMMIT, MO 64063510 NW MAIN ST, LEES SUMMIT, MO 64063			
This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.					
Item:	Inspector:	Outcome:	Date:		
•	Steve Robbins	Partial	Tuesday, February 18, 2020		
MH A-1 has been " pipe was ran the "stalled to conne we was ok with the he flow line. This	nrough the MH and the Act the new pipe on both set the new pipe on both set pipe staying in as long at its not a doghouse MH be	lok's and a fernco stainles sides of the MH. I spoke wi as they cut the top off and ecause the botton of the M	s steel strongback was ith Brent at water and kept the bottom for		
on Inspection	Steve Robbins	Partial	Tuesday, February 18, 2020		
nstalled the first Iso wrapped the	MH and have backfilled,		•		
	ry Sewer on Inspection  al MH A-1 has been by pipe was ran the nstalled to conne we was ok with the he flow line. This will pour the inve  ry Sewer on Inspection  al nstalled the first Iso wrapped the	ry Sewer Steve Robbins on Inspection  al MH A-1 has been installed. The existing 8" "pipe was ran through the MH and the Anstalled to connect the new pipe on both see was ok with the pipe staying in as long as the flow line. This is not a doghouse MH be will pour the inverts aroud the pipe and curry Sewer Steve Robbins on Inspection  al al anstalled the first service line, installed treated the service line, installed the first service line, installed the first service line, installed the sert. Steve Robbins 02/18/2020 4:16 PM	ry Sewer Steve Robbins Partial on Inspection  al MH A-1 has been installed. The existing 8" line was cut and the MH vill pipe was ran through the MH and the A-lok's and a fernco stainles installed to connect the new pipe on both sides of the MH. I spoke we was ok with the pipe staying in as long as they cut the top off and the flow line. This is not a doghouse MH because the botton of the Mill pour the inverts aroud the pipe and cut off the top of the pipe.  The sewer steve Robbins Partial on Inspection  al installed the first service line, installed trench check, anode and trace is owrapped the MH and have backfilled, they were installing the lide of the Steve Robbins 02/18/2020 4:16 PM		