CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182607

Address: 829 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Mark Harding Partial Tuesday, March 31,

2020

Corrective Action Required:

1 STAIR TOWER 1 INTERIOR WALLS, 2 LAYERS.

STAIR UNDERSIDE-OK

LOWER LEVEL-SOUTH WALL-2ND LAYER OK

OUTER SIDE:

LOWER FL-2ND LAYER OK 1ST FL- 1ST LAYER OK 2ND FL-2ND LAYER OK

3RD FL 4TH FL

Corrective Action Required:

2 STAIR TOWER 2 INTERIOR WALLS. 2 LAYERS

STAIR UNDERSIDE-OK

OUTER SIDE:

LOWER FL-2ND LAYER OK 1ST FL-1ST LAYER OK 2ND FL-2ND LAYER OK

3RD FL-4TH FL-

Corrective Action Required:

3 ELEVATOR 1 1ST,2ND LAYER ELEVATOR SHAFT INSIDE

1st layer outside, exterior 1st layer

CEIILING 1,2,3,HAT CHANNEL.4th layer.

OUTER SIDE:

LOWER FL-2ND LAYER OK 1ST FL-1ST LAYER OK 2ND FL-2ND LAYER OK

3RD FL-4TH FL-

Informational:

4 FOURTH FLOOR

UNITS AND CORRIDORS

Informational:

5 THIRD FLOOR RC-

1ST,2ND LAYERS AT STAIRS AND ELEVATOR WALLS.

Wall type X & ceiling type C screw patterns units & corridors

Fire collars roof drains (4) bedroom closets

Informational:

6 SECOND FLOOR

complete

Informational:

7 FIRST FLOOR complete

Corrective Action Required:

8 LOWER LEVEL RC garage ceilings OK

RC CORRIDOR&ROOMS OK

BOTH GARAGES AT ENDS OF BUILDING-CEILING PREROCK OK BEFORE SE CABLE

FUR-DOWN. SE PENETRATIONS ARE FIRE-CAULKED

SHEAR WALL 4-2ND LAYER OK ON BOTH SIDES

SHEAR WALL 2-ALL ROOMS ALONG CORRIDOR WALL-2ND LAYER OK

ELEVATOR EQUIPMENT ROOM:

CEILING-1,2,3RD

Comments: