

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182609
Address: 833 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Mark Harding	Partial	Friday, April 03, 2020

Partial Correction:

1	ELEVATOR 1	OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT ELEVATOR SHAFT: 1ST LAYER 1-4, 2nd layer, ceiling 2nd; SPACES BETWEEN JOISTS AT BACKSIDE: BASEMENT: 1ST FLOOR: 1ST LAYER; 2ND LAYER; 2ND FLOOR: 1ST LAYER; 2ND LAYER 3RD FLOOR: 1ST LAYER; 2ND LAYER 4TH FLOOR:
---	------------	---

Corrective Action Required:

2	STAIR TOWER 1	SPACES BETWEEN JOISTS AT BACKSIDE: 3RD FLOOR 1ST BASEMENT- EXTERIOR: 4TH FL- CEILING;2ND,3rd and hat channel INTERIOR SIDE: 4TH FL-1ST LAYER;2ND BASEMENT-1ST LAYER OK
---	---------------	--

		OUTER SIDE:
Corrective Action Required:		
3	STAIR TOWER 2	SPACES BETWEEN JOISTS AT BACKSIDE: 3RD- FLOOR 1ST
		CEILING;2ND,3rd and hat channel
		INTERIOR SIDE:
		4TH FL-1ST LAYER;2ND
		BASEMENT-1ST LAYER OK
Corrective Action Required:		
4	FOURTH FLOOR	Pre rock tub & showers 4th floor approved 1ST 2ND AT STAIR TOWNERS
Corrective Action Required:		
5	THIRD FLOOR	Pre rock tub & showers 3rd floor approved
Corrective Action Required:		
6	SECOND FLOOR	TUB SHOWERS - 1ST; 2ND Layer
Corrective Action Required:		
7	FIRST FLOOR	TUB SHOWERS - 1ST; 2ND Layer
Corrective Action Required:		
8	LOWER LEVEL	Elevator Equip, IT, Electrical rooms-2nd layer ok

Comments: