CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182604 Address: 837 NW DONOVAN RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | Inspector: | Outcome: | Date: |
|---------------------------|--|----------|-------------------------------|
| Rated Assembly Inspection | John Borns | Failed | Thursday, October 03, 2019 |
| Partial Correction: | | | |
| 1 Misc | OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT WALLS INSIDE FACE AND SPACES BETWEEN JOISTS AT BACKSIDE: STAIRWELL 1: 1ST FLOOR: 1ST LAYER; 2ND LAYER; | | |
| | 2ND FLOOR: 1ST LAYER; 3RD FLOOR: 1ST LAYER N | • | |
| | STAIRWELL 2: | | |
| | 1ST FLOOR: 1ST LAYER; 2ND LAYER; 2ND FLOOR: 1ST LAYER; 2ND LAYER @ 2 OF 3 WALLS; STAIRWELL 3: 1ST FLOOR: 1ST LAYER; 2ND LAYER; 2ND FLOOR: 1ST LAYER; 2ND LAYER @ 2 OF 3 WALLS; | | |
| | STAIRWELL 4: 1ST FLOOR: 1ST LAYER; 2ND LAYER; 2ND FLOOR: 1ST LAYER; 2ND LAYER; 3RD FLOOR: 1ST LAYER NOT COMPLETED; | | |

NOTE: FIRESTOPPING WHERE PVC PIPE INTERRUPTS GWB IS SUBJECT TO APPROVAL WHEN COMPLETED. 2 Misc OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB @ ELEVATOR SHAFT SPACES BETWEEN JOISTS AT BACKSIDE: EAST ELEVATOR: 1ST FLOOR: 1ST & 2ND LAYERS; WEST ELEVATOR: 1ST FLOOR: 1ST & 2ND LAYERS;

Comments: