CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20182611

Address: 901 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Robb Popp Partial Tuesday, May 26, 2020

Partial Correction:

THE FOLLOWING BEHIND TUBS AND SHOWERS FIRST LAYER FLOORS 1-4

AREAS ARE BEHIND TUBS AND SHOWERS SECOND LAYER FLOORS 1-4

APPROVED ELEVATOR AND STAIRWELL FIRST LAYER FLOORS 1-4

SHEAR WALL FIRST LAYER BEHIND TUBS AND SHOWER FLOORS 1-2

SHEAR WALL 6 FIRST LAYER OSB FLOORS 1-2

SHEAR WALL4 FIRST LAYER SHEAR WALL 2 FIRST LAYER SHEAR WALL 6 FIRST LAYER

ELEVATOR EQUIPMENT ROOM LOWER LEVEL FIRST LAYER

MECHANICAL ROOM LOWER LEVEL FIRST LAYER

CORRIDOR FIRST LAYER ROOM SIDE LOWER LEVEL AND FIRST FLOOR

Partial Correction:

2 STAIR TOWER 1 4TH FLOOR 1ST LAYER;

- 4TH FLOOR 2ND LAYER -

-CEILING AND WALL TOP OUT 1ST LAYER-

-CEILING AND WALLS 2ND LAYER

MECHANICAL ROOMS 2ND LAYER CEILING

3RD LAYER AND HAT CHANNEL

Partial Correction:

3 STAIR TOWER 2 4TH FLOOR 1ST LAYER;

- 2ND LAYER FLOORS 1-4 -

-CEILING AND TOP OUT 1ST LAYER

CEILING AND WALLS 2ND LAYER

MECHANICAL ROOM 2ND LAYER CEILING

3RD LAYER AND HAT CHANNEL

Partial Correction:

4 ELEVATOR 1 OK TO COVER WHEN READY 5/8" MOLD-RESISTANT FIRECODE X GWB AT

ELEVATOR SHAFT:

1ST LAYER FLOORS: 1-4 CEILING:1ST, LAYER - 2ND LAYER FLOORS 1-4 CEILING 2ND LAYER -

CEILING 3RD LAYER AND HAT CHANNEL

CEILING 4TH LAYER

Partial Correction:

5 FOURTH FLOOR
Corrective Action Required:
6 THIRD FLOOR
Corrective Action Required:
7 SECOND FLOOR
Corrective Action Required:

FIRST FLOOR 1ST FLOOR ELEC ROOM, IT ROOM, ELEV EQIP ROOMS 1ST LAYER -

Corrective Action Required:
9 LOWER LEVEL

Comments: