CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20182613 Address: 905 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Thursday, July 16, 2020
Partial Correction:				
1	STAIR TOWER 1	OK TO COVER WHEN READ	OY COMPONENTS OF RATED	ASSEMBLY AT STAIRS:
		WELL FACE, 3RD FL 1ST LAY	′ER,4TH,	
		STAIR #1:		
		WELL FACE + BACKSIDE AB		
		1ST FLOOR 1ST & 2ND LAY		
		2ND FLR 1ST & 2ND LAYER	,	
		3rd FLOOR 1ST LAYER, 2ND		
			ILING 1ST LAYER, 2ND LAYEF	{
		3rd LAYER and HAT ON CEI		
		4TH LAYER ON UPPER AND	LOWER CEILINGS	
Partial Correction:				
2	STAIR TOWER 2	STAIR #2:		
		WELL FACE + BACKSIDE AB		
		1ST FLOOR 1ST & 2ND LAY 2ND FLR 1ST & 2ND LAYER		
		ZND FLR IST & ZND LATER.	2	
		WELL FACE, 3RD FL 1ST LAY	′ER,4TH	
		·	EILING 1ST LAYER, 2ND LAYE	ĨR
		3rd LAYER and HAT ON CEI		
		4TH LAYER ON UPPER AND	LOWER CEILINGS	

Corrective Action Required: 3 ELEVATOR 1		OK TO COVER WHEN READY COMPONENTS OF RATED ASSEMBLY AT		
		ELEVATOR:		
		PRE-ROCK @ BACKSIDE ABV CLG:		
		1ST FLOOR 1ST & 2ND LAYERS		
		2ND FLOOR 1ST & 2ND LAYERS		
		3RD FLOOR: 1ST LAYER;2ND LAYERS		
		- ELEVATOR SHAFT -		
		- FIRST LAYER ALL FLOORS & CEILING -		
		-2ND LAYER		
		-THIRD LAYER AND HAT CHANNEL CEILING		
		-FOURTH LAYER CEILING		
Corrective Action Required:				
4	FIRST FLOOR	- BEHIND TUBS/SHOWERS 1ST LAYER FIRE CAULK -		
		-SECOND LAYER BEHIND TUBS/SHOWERS AT CORRIDOR WALLS AND SHEAR WALL4		
		-FIRST LAYER CORRIDOR WALLS, STAIRWELL WALLS AND ELEVATORS WALLS		
Corrective Action Required:				
5	SECOND FLOOR	- BEHIND TUBS/SHOWERS 1ST LAYER/ FIRE CAULK -		
		-SECOND LAYER BEHIND TUBS/SHOWERS AT STAIRWELLS, ELEVATOR WALLS,		
		SHEAR WALLS 4 AND 6		
		-FIRST LAYER BEHIND STAIRWELLS AND ELEVATOR		
Corrective Action Required:				
6	THIRD FLOOR	- BEHIND TUBS/ SHOWERS 1ST LAYER FIRE CAULK -		
		-SECOND LAYER BEHIND TUBS/SHOWERS AT STAIRWELLS, AND ELEVATOR		
		-FIRST LAYER BEHIND STAIRWELLS AND ELEVATOR		
Correctiv	e Action Required:			
7	FOURTH FLOOR	-ELEVATOR EQUIPMENT ROOM 1ST AND 2ND LAYER WALLS		
		-DATA ROOM 1ST AND 2ND LAYER WALLS		
		-ELECTRICAL/DATA ROOM 1ST AND 2ND LAYER WALLS		
		- BEHIND TUBS/SHOWERS 1ST LAYER / FIRE CAULK -		
		-SECOND LAYER BEHIND TUBS AND SHOWERS AT STAIRWELLS, ELEVATOR AND		
		SHEAR WALL 4		
		-1ST AND 2ND LAYER MECHANICAL ROOMS WALLS AND CEILING		
		3rd LAYER AND HAT ON CEILING IN MECHANICAL ROOMS		
		4TH LAYER ON CEILING IN MECHANICAL ROOMS		
		-FIRST LAYER BEHIND STAIRWELLS AND ELEVATOR		
		-RC CHANNEL WALLS AND CEILING COMPLETE		
Corrective Action Required:				
8	LOWER LEVEL			

Comments: