CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096 Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
All Rough Inspection - Commercial		Robb Popp	Partial	Friday, August 14, 2020
Corrective Action Required: 1 FOURTH FLOOR		AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462–460- 426-		
Corrective 2	e Action Required: THIRD FLOOR	Corridor 419 to room 439 ok Corridor 422 to stairs ok		
		-CORRIDOR 426 AND 427 CEILING FRAMING OK		
		Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing ceiling		
Corrective 3	e Action Required: SECOND FLOOR	Corridor 319 to room 364 ok Corridor 322 to stairs ok		
		-CORRIDOR 326 AND 327 CEILING FRAMING OK		
		Section "E" Ok-240,241,242,243,244,245,261,262. 226.		
		Corridor 219 to room 240 o Corridor 222 to stairs ok	ok	

	-264- shower valve box corridor wall incomplete		
	-CORRIDOR 326 AND 327 CEILING FRAMING OK		
Corrective Action Required: 4 FIRST FLOOR	Section "E" OK-125, 126, 127, 128, 129, 133, 134		
	Corridor 119 to room 125 ok		

Corridor 119 to room 125 ok Corridor 122 to stairs ok -Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-FASTEN ANCHOR BOLT BY WINDOW

-SEAL TOP OF WALL AT DEMISING WALL/ CORRIDOR

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments: