

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Tuesday, August 18, 2020

Corrective Action Required:

1	FOURTH FLOOR	AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426- -444,447,450,451,457 -SEAL GAP AT TOP PLATES BETWEEN WALLS IN 448,447
---	--------------	---

Corridor 419 to room 439 ok
Corridor 422 to stairs ok

-CORRIDOR 422,426, 427

Corrective Action Required:

2	THIRD FLOOR	Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing ceiling
---	-------------	---

Corridor 319 to room 364 ok
Corridor 322 to stairs ok

-CORRIDOR 326 AND 327 CEILING FRAMING OK

Corrective Action Required:

3	SECOND FLOOR	Section "E" Ok-240,241,242,243,244,245,261,262. 226, 264
---	--------------	--

Corridor 219 to room 240 ok
Corridor 222 to stairs ok

Corrective Action Required:
4 FIRST FLOOR

-CORRIDOR 326 AND 327 CEILING FRAMING OK

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2- BRACE TOP OF WALL PER PLANS. ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 132, 133, 134, 135

Corridor 119 to room 125 ok
Corridor 122 to stairs ok

-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments: