

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Robb Popp	Partial	Thursday, August 20, 2020

Corrective Action Required:

1	FOURTH FLOOR	AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426- -444,447,448,449,450,451,457,424A Corridor 419 to room 439 ok Corridor 422 to stairs ok
---	--------------	--

-CORRIDOR 422,426, 427

Corrective Action Required:

2	THIRD FLOOR	Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing ceiling Corridor 319 to room 364 ok Corridor 322, 326, 327 -346 NO ACCESS -UNITS-COMplete SHOWER PANS THROUGHOUT, PROVIDE STRAP AT TOP PLATE WHERE DWV BORED MORE THAN 50% AND PROVIDE STUD FOR PROPER JOIST BEARING AT ALL LOCATIONS 360- NAIL THROUGH NM IN BATHROOM 348- SEAL PENETRATIONS IN TOP PLATE, PROVIDE FIREBLOCKING AT TUB
---	-------------	--

Corrective Action Required:

3 SECOND FLOOR Section "E" Ok-240,241,242,243,244,245,261,262. 226, 264,

Corridor 219 to room 240 ok

Corridor 222 to stairs ok

-CORRIDOR 326 AND 327 CEILING FRAMING OK

Corrective Action Required:

4 FIRST FLOOR BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 132, 133, 134, 135

Corridor 119 to room 125 ok

Corridor 122 to stairs ok

-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments: