CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Partial Friday, August 21, 2020

Commercial

Corrective Action Required:

1 FOURTH FLOOR AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426-

-444,447,448,449,450,451,457,424A

Corridor 419 to room 439 ok Corridor 422 to stairs ok

-CORRIDOR 422,426, 427

Corrective Action Required:

THIRD FLOOR Section "E"

345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing

ceiling

-321A, 324A, 347, 348, 349, 350, 351, 352, 353, 354, 356, 357, 358, 359, 360

Corridor 319 to room 364 ok

Corridor 322, 326, 327

-346 NO ACCESS

-355 PROVIDE STRAP AND BEARING STUD AT DWV

Corrective Action Required:

3 SECOND FLOOR Section "E" Ok-240,241,242,243,244,245,261,262. 226, 264,

Corridor 219 to room 240 ok

Corridor 222 to stairs ok

-CORRIDOR 326 AND 327 CEILING FRAMING OK

Corrective Action Required:

FIRST FLOOR

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 132, 133, 134, 135

Corridor 119 to room 125 ok
Corridor 122 to stairs ok
Corridor 136 Matal Stad Francisco franco a arthur status line

-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments: