

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Commercial</b>	Robb Popp	Partial	Monday, August 24, 2020

Corrective Action Required:

1	FOURTH FLOOR	AREA "E" - UNITS-438439,440,461,441,442,459-443-459-461-462-460- 426- -444,447,448,449,450,451,457,424A, 425A Corridor 419 to room 439 ok Corridor 422 to stairs ok  -CORRIDOR 422,426, 427
---	--------------	--

Corrective Action Required:

2	THIRD FLOOR	Section "E" 345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing ceiling -321A, 324A, 325A, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360 Corridor 319 to room 364 ok Corridor 322, 326, 327  -346 NO ACCESS -355 PROVIDE STRAP AND BEARING STUD AT DWV
---	-------------	---

Corrective Action Required:

3	SECOND FLOOR	Section "E" Ok-240,241,242,243,244,245,261,262. 226, 264,
---	--------------	---

Corridor 219 to room 240 ok  
Corridor 222 to stairs ok

Corrective Action Required:  
4 FIRST FLOOR

-CORRIDOR 326 AND 327 CEILING FRAMING OK

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 \*\* METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL \*\*METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 132, 133, 134, 135

Corridor 119 to room 125 ok

Corridor 122 to stairs ok

-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

**Comments:**