

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Mark Harding	Partial	Tuesday, August 25, 2020

Corrective Action Required:

1	Miscellaneous Correction	RETAIL AREA "B"
		-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR SHEATHING SCREW PATTERN

Corrective Action Required:

2	FIRST FLOOR	AREA "E"
		-AREAS APPROVED-

RC CHANNEL ROOMS 124,125,126,127,128,129,133,134,135 WALLS AND CEILING

Corrective Action Required:

3	SECOND FLOOR	AREA "E"-AREAS APPROVED- CORRIDORS- 222 RC CHANNEL , 1ST LAYER; 226 RC CHANNEL , 1ST LAYER;
---	--------------	---

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS: 241,242,243,244,245,262,262,263; 240,264

Corrective Action Required:

4

THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL WALLS AND CEILINGS 340,364

RC CHANNEL CORRIDOR 322 TO CORRIDOR 326

RC CHANNEL CORRIDOR 326 AND 327

SCREW PATTERN ON CEILING CORRIDOR 322

SCREW PATTERN ON CEILING CORRIDOR 326 TO ROOM 355

SCREW PATTERN ON FIRST LAYER WALLS CORRIDOR 319 TO ROOM 341,  
CORRIDOR 322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST LAYER CORRIDOR AND DIMISING WALLS:  
341,342,343,344,345,361,362,363

Corrective Action Required:

5

FOURTH FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL WALLS AND CEILING 438-453, 459-462

RC CHANNEL CORRIDOR 422, CORRIDOR 426

RC CHANNEL CORRIDOR 427

SCREW PATTERN ON FIRST AND SECOND LAYER WALLS CORRIDOR 419 TO  
ROOM 439

SCREW PATTEN ROOMS AND SECOND LAYER DIMISING WALL  
439,440,441,442,443,459,460,461

Corrective Action Required:

6

STAIR TOWER 1

STAIR TOWER "A"

AREAS OK:

-1ST LAYER SHEATHING TO 3RD FLOOR;

-2ND LAYER SHEATHING TO 3RD FLOOR

Corrective Action Required:

7

ELEVATOR 2

ELEVATOR "B"

AREAS OK:

-SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)

**Comments:**