

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Rated Assembly Inspection	Robb Popp	Partial	Thursday, August 27, 2020

Corrective Action Required:

1	Miscellaneous Correction	RETAIL AREA "B"
---	-----------------------------	-----------------

-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR
SHEATHING SCREW PATTERN

Corrective Action Required:

2	FIRST FLOOR	-AREAS APPROVED- AREA "E"
---	-------------	------------------------------

RC CHANNEL ROOMS 124,125,126,127,128,129,133,134,135 WALLS AND
CEILING
UNITS-126

Corrective Action Required:

3	SECOND FLOOR	\-AREAS APPROVED- AREA "E"
---	--------------	-------------------------------

CORRIDORS-RC CHANNEL 222,226 .
1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO
ROOM 241, CORRIDOR 222 TO STAIRS

Corrective Action Required: 4	THIRD FLOOR	1ST LAYER UNITS: 241,242,243,244,245,262,262,263; 240,264 AREA "E"
		-AREAS APPROVED-
		RC CHANNEL - 321A,340,364 RC CHANNEL CORRIDORS- 322,326,327,319
		1ST LAYER CEILING- 322, 326 TO ROOM 355.
		1ST LAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS
		SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS: 341,342,343,344,345,361,362,363
Corrective Action Required: 5	FOURTH FLOOR	-AREAS APPROVED- AREA "E" RC CHANNEL WALLS AND CEILING 438-453, 459-462 RC CORRIDOR 421A,422, 426, 427
		SCREW PATTERN 1ST, 2ND LAYER WALLS CORRIDOR 419 TO ROOM 439 SCREW PATTEN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS: 439,440,441,442,443,459,460,461
Corrective Action Required: 6	STAIR TOWER 1	STAIR TOWER "A" AREAS OK: -1ST LAYER SHEATHING TO 3RD FLOOR; -2ND LAYER SHEATHING TO 3RD FLOOR
Corrective Action Required: 7	ELEVATOR 2	ELEVATOR "B" AREAS OK: -SHEATHING ON NORTH AND SOUTH WALLS (TYPE A) -FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS

Comments: