# CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

# **DEVSERVICES.CITYOFLS.NET**

# **Inspection Summary**

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Robb Popp Partial Thursday, August 27,

Commercial 2020

Corrective Action Required:

1 FOURTH FLOOR AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460-

426;444,447,448,449,450,451,457,424A, 425A

Corridor 419 to room 439 ok -CORRIDOR 419,422,426, 427

Corrective Action Required:

2 THIRD FLOOR Section "E"

345-344-343- 342-361-362-363-341-364-340-322-326-327-corridor framing

ceiling

-321A, 324A, 325A, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357,

358, 359, 360

Corridor 319 to room 364 ok Corridor 322, 326, 327

Corrective Action Required:

3 SECOND FLOOR Section "E" Ok-240,241,242,243,244,245,261,262. 226, 264,

-,247,249,251,256,257,258,259,260,

-250-FINISH DWV DRAIN LINE BY PATIO

-252-PROVIDE BOTTOM PLATE AT BEARING STUD, SEAL DEAD SPACE

-253-SEAL DEAD SPACE

-254-STRAP TOP PLATE, TIE EXTERIOR WALLS TOGETHER AT CORNER

### -255 COMPLETE SERVICE CABLES

Corridor 219 to room 240 ok Corridor 222 to stairs ok

-CORRIDOR 326 AND 327 CEILING FRAMING OK

Corrective Action Required: 4 FIRST FLOOR

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 \*\* METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL \*\*METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 132, 133, 134, 135

Corridor 119 to room 125 ok Corridor 122 to stairs ok

-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

## Comments: