

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Commercial	Michael Harkins	Partial	Tuesday, September 01, 2020

Corrective Action Required:

1 FOURTH FLOOR AREA"E"- UNITS-438439,440,461,441,442,459-443-459-461-462-460-426;444,447,448,449,450,451,457,424A, 425A
Corridor 419 to room 439 ok
-CORRIDOR 419,422,426, 427, 429,

AREA "D"
CORRIDOR 412,

Corrective Action Required:

2 THIRD FLOOR Section "E"
345-344-343- 342-361-362-363-341-364-340-322-326-327, 329, -corridor framing ceiling
-321A, 324A, 325A, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360
Corridor 319 to room 364 ok
Corridor 322, 326, 327, 329,

SECTION "D"
CORRIDOR FRAMING CEILING 312,

Corrective Action Required:

3 SECOND FLOOR Section "E" Ok- 224A, 240,241,242,243,244,245, 246, 261,262. 225A, 226, 264, -,247,249,250,251,252, 253,254,256,257,258,259,260,

-248- SEAL DEAD SPACE AT FUTURE SHAFT

Corridor 219 to room 240 ok
Corridor 222 to stairs ok
SECTION "E"
CORRIDOR FRAMING CEILING 229,

SECTION "D"
CORRIDOR CEILING FRAMING 212,

Corrective Action Required:

4 FIRST FLOOR

BUILDING "B"

-CORRIDOR 103 LINE 4.3 TO 2 ** METAL FRAMING ONLY

BUILDING "C" AREAS OK;

-LOBBY EXTERIOR EAST WALL **METAL FRAMING ONLY

Section "E" OK-124,125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135

Corridor 119 to room 125 ok
Corridor 122 to stairs ok
CORRIDOR CEILING 112, 129,
-Corridor 126 Metal Stud Framing from north exit to line 8.6

-CORRIDOR 124- PROVIDE HANGERS/ CONNECTIONS ON FLOOR JOISTS BOTH ENDS-

-ROOM 132-

-SEAL HOLE IN CORRIDOR WALL AT CLEAN OUT

Comments: