

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20192096  
Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Michael Harkins	Partial	Thursday, October 08, 2020

Corrective Action Required:

1	Miscellaneous Correction	RETAIL AREA "B"
		-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR SHEATHING SCREW PATTERN

Corrective Action Required:

2	FIRST FLOOR	-AREAS APPROVED- AREA "E"
---	-------------	------------------------------

RC CHANNEL CEILING 112,129,  
RC CHANNEL WALLS AND CEILINGS CORRIDORS 119,122, 129 -  
RC CHANNEL ROOMS 120A,121A,124,125,126,127,128,129, 130, 131,  
133,134,135 WALLS AND CEILING -  
- 120A, 1ST LAYER/2ND LAYER BEHIND PANEL -  
- 142 1ST LAYER BEHIND PANEL -  
- 141 1ST/2ND LAYER EAST WALL BEHIND PANEL,  
1ST LAYER/2ND LAYER EAST WALL BEHIND SWITCH GEAR -

- 1ST LAYER 121A, 124,125,127,128,129, 130,131, 132, 133,134, 135, 1ST LAYER CORRIDOR AT THESE UNITS -

2ND LAYER UNITS 121A,124,125,126,127,128,129,130,131,132,133,134, 135, -  
- CORRIDOR 119 1ST LAYER/2ND LAYER BOTH SIDES -  
- CORRIDOR 122 1ST LAYER/ 2ND LAYER BOTH SIDES, LID PREROCK -  
- CORRIDOR 129 (LID) PREROCK -

Corrective Action Required:

3

SECOND FLOOR

\-AREAS APPROVED-  
AREA "E"

RC CHANNEL WALLS AND CEILINGS:

CORRIDORS 219

222,226, 227, 221A,240-245,261-264,265,266,267 -

- RC CHANNEL CORRIDOR 212 CEILING ONLY -

- RC CHANNEL CORRIDOR 229 WALLS & CEILING -

1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO  
ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS: 224A,221A,224A,225A,240,241,242,243,244,245,246,  
247,248,249,250,251,252,253,254,255,256,257,258,  
259,260,262,263,264-

- 2ND LAYER UNITS 221A,224A,225A,236,240,241,242,243,  
244,245,246,247,248,249,250,251,252,253,254,255,  
256,257,258,259,260,262,263, 264, -

- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -

- 1ST LAYER MECHANICAL CHASES 2ND FLOOR -

- 2ND LAYER MECHANICAL CHASES 2ND FLOOR -

- "E" RC CHANNEL CEILINGS & WALLS

224A,225A,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260, -

- CORRIDOR 222 2ND LAYER BOTH SIDES -

- CORRIDOR 226 1ST & 2ND LAYER WEST WALL -

- CORRIDOR 226 1ST LAYER EAST WALL (EXCEPT CHASES ) -

- CORRIDOR 227, CEILING 1ST LAYER WALLS -

- CORRIDOR 229 CEILING, 1ST LAYER -

:AREA "D":

- CORRIDOR 212 (LID)

Corrective Action Required:

4

THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL - 320A,321A,340,364

RC CHANNEL CORRIDORS- 322,326,327,319  
RC CHANNEL CORRIDOR 329 WALLS & CEILING -  
- RC CHANNEL  
324A,325A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360,3  
65,366,367 -

1ST LAYER CEILING- 322, 326 TO ROOM 355.

1ST LAYER WALLS CORRIDORS 319 TO ROOM 341, 322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND  
DIMINISHING WALLS:

326,341,342,343,344,345,361,362,363

- RC CHANNEL

324A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

- 1ST LAYER UNIT 321A,324A,325A,340,  
346,347,348,349,350,351,352,353,354,355,356,357,  
358,359,360,364, -

- 2ND LAYER UNIT 321A,324A,325A,340,347,348,349,350,351,352,353,  
354,356,357,358,359,360, 364, -

- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -

- 3RD FLOOR MECHANICAL CHASE 1ST LAYER/2ND LAYER COMPLETE -

- CORRIDOR 319 1ST LAYER/2ND LAYER -

- CORRIDOR 322 1ST LAYER/2ND LAYER WALLS -

- CORRIDOR 326 1ST LAYER/2ND LAYER WEST WALL,  
1ST LAYER/2ND LAYER EAST WALL -

- CORRIDOR 327 WALLS & CEILING -

- CORRIDOR 329 LID, 1ST LAYER -

- AREA "D" -

- CORRIDOR 312 RC CHANNEL CEILING -

- CORRIDOR 312 LID -

- UNIT 332 LIDS FOR DUCTS LAUNDRY & CLOSET -

Corrective Action Required:

5 FOURTH FLOOR

4TH FL- -AREAS APPROVED-

AREA "E" RC CHANNEL AREAS:

-RC CHANNEL UNITS: 420A,437,438-453,

459-462,-424,425A,414A,444,445,446,447,448,449,450,451,452,453,454,455,  
456,457,463,464 -

- RC CHANNEL CEILING ONLY 420,437,463,464,465, -

-RC CORRIDOR 421A,422, 426, 427,

-CORRIDOR 429 WALLS & CEILING -

- AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST, 2ND  
LAYER ;

FIRE TAPE COMPLETE -

- BLDG "E" PHASE 2 UNITS:

1ST LAYER

:424A,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458 -438,  
462, 421A,424A, 425A -

2ND LAYER: 444,445,446,447,448,449,450,451,452,453,454,455,  
456,457,458, 438, 462,421A,425A -

- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -

- 420A PREROCK CORRIDOR WALL WALL LAYER -

- CORRIDOR 419 1ST/2ND LAYER;

FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS:

439,440,441,442,443,459,460,461

- CORRIDOR NUMBERS #:

- 429 LID,1ST LAYER -

;439,440,441,442,443,459,460,461;

- WALLS:

422 1ST, 2ND LAYER-;

- 426 1ST,& 2ND LAYER WEST WALL-;

- 426 1ST & 2ND LAYER EAST WALL -

- CORRIDOR 427 WALLS & CEILING -

" D"

- CORRIDOR 412 RC CHANNEL CEILING -

Corrective Action Required:

6

STAIR TOWER 1

STAIR TOWER 107 "A" SOUTH AREA "B"  
AREAS OK:

-1ST LAYER SHEATHING TO 3RD FLOOR;

-2ND LAYER SHEATHING TO 3RD FLOOR:

- 1ST LAYER SHEATHING 4TH FLOOR -

Corrective Action Required:

7

ELEVATOR 2

ELEVATOR 118 "B" WEST CENTER AREAS INSPECTED:

AREAS OK:

-SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)

-FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS -

- 2ND LAYER "B" ELEVATOR WALLS

- 1ST LAYER "B" 3RD & 4TH FLOOR SHAFT WALL-

- 2ND LAYER "B" 3RD & 4TH FLOOR SHAFT WALL -

Corrective Action Required:

8

ELEVATOR 3

ELEVATOR 128 "C" NORTH EAST-AREAS INSPECTED:

- ELEVATOR 128" C " -

- 1ST LAYER WEST WALL 2ND,3RD,4TH FLOORS -

- 2ND LAYER WEST WALL 2ND, 3RD & 4TH FLOORS-

- 1ST LAYER 4TH FLOOR SOUTH WALL SHAFT & EXTERIOR WALL -

- ELEVATOR C 4TH FLOOR SHAFT WALL 2ND LAYER CEILING TO 8', 8' TO ACCESS  
HOLE IN CORRIDOR -

- ELEVATOR SHAFT 1ST LAYER 4TH FLOOR, 3RD FLOOR, 2ND FLOOR -

- ELEVATOR SHAFT 2ND LAYER 4TH, 3RD, 2ND -

Corrective Action Required:

9 STAIR TOWER 2

STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:

Corrective Action Required:

10 STAIR TOWER 3

STAIR TOWER 123 "C" NORTH

AREAS INSPECTED:

- 1ST LAYER FLOORS 1 THRU 4 -

- 2ND LAYER FLOORS 1 THRU 4 -

- CEILING -

- RC CHANNEL CEILING -

Corrective Action Required:

11 ELEVATOR 1

ELEVATOR 102 "A" SOUTH CENTER AREAS INSPECTED:

**Comments:**