CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20193016 Address:

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|-----------------------------|---|--|---------------------------|--------------------------------|
| Storm - Outlet Structure | | Ronald Paynter | Passed | Wednesday, October 28, 2020 |
| Informational: | | | | |
| 1 Informat | Misc Cory's crew set curb inlet 101. RP 8-17-20 ational: | | | |
| 2 Informat | Misc ional: | Cory's crew set curb inlets 102 and 103. RP 8-19-20 | | |
| 3 | Misc | Cory's crew set curb inlet 104. They poured collars and inverts for curb inlets 101, 102, 103 and 104. They started breaking rock for curb inlet 200. RP 8-20-20 8-26-20 ESS have set storm box A1 with 60' of pipe. They will pour collars and inverts on 8-27-20 | | |
| Corrective Action Required: | | | | |
| 4 | Misc | ESS turned the top section of storm structure 401 a 1/4 turn. This turn has caused the steps to become misaligned. Had a Zoom meeting with Kent Monter and Cutter Gale. Explained the options (steps on east or west side of structure or make a new top section with 2 instead of 3 openings at the top). Cutter is going to follow up with what they believe is best for the structure and Gale Communities. RP 9-17-20 | | |
| Informat | ional: | | , _, | |
| 5 | Misc | Structure has been install | ed correctly. RP 10-28-29 | |

Comments: