CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20200845 Address: 80 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

| Inspection: | | Inspector: | Outcome: | Date: |
|-----------------------------|----------------------------|---|----------|---------------------------------|
| Rated Assembly Inspection | | Robb Popp | Partial | Wednesday, November 04, 2020 |
| Corrective Action Required: | | | | |
| 1 | THE FOLLOWING AREAS ARE | RATED ASSEMBLY- | | |
| | APPROVED | TOP OUT OF WALLS ONLY: | | |
| | | 1ST LAYER, 2ND LAYER- CORRIDOR 02-B00N, B00P; EXTERIOR OF ROOM B080 | | |
| | | CORNER OF 1-B000,1-B00 | P; 1B007 | |
| FOLLOWING ROOMS: 1ST LAYER | | | | |
| | | 49,60,61,62; 1st layer door to ambulance bay | | |
| | | SHAFT WALL 1HR RM 1B076,77 complete. | | |
| | | 1st layer 1b-078, | | |
| | | 1st layer rm 174 | | |
| | | Shaft layer columns: room 80,82,84 | | |
| | | 1st layer columns room 80,82 | | |
| | | -1st Layer walls room 80 | | |
| | | Shaft layer columns room 075 | | |
| | | 1st layer columns room 07 | /5 | |
| | | EMERGENCY: | | |
| | | 1st Layer corridor B102 Eas | st Wall | |
| | | | | |

CORRIDOR 02-1B00N

-Shaft layer at ceiling of stairwell doorway

-First layer at ceiling of stairwell doorway

-Corridor walls first layer from vestibule door to stairwell doorway

Comments: