CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20192096

Address: 940 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Michael Harkins Partial Wednesday, October

21, 2020

Corrective Action Required:

1 Miscellaneous

RETAIL AREA "B"

Correction

-AREAS APPROVED-

-CORRIDOR 103 WEST WALL FROM COLUMN LINE 2 TO 4.4 EXTERIOR

SHEATHING SCREW PATTERN

Corrective Action Required:

2 FIRST FLOOR

-AREAS APPROVED-

AREA "E"

-112 RC CHANNEL CEILING, SCREW PATTERN LID -

- 129 RC CHANNEL CEILING,

RC CHANNEL WALLS AND CEILINGS CORRIDORS 119,122, 129 - RC CHANNEL ROOMS 120A,121A,124,125,126,127,128,129, 130, 131,

133,134,135,136,137,138,WALLS AND CEILING - 120A, 1ST LAYER/2ND LAYER BEHIND PANEL -

- 142 1ST LAYER BEHIND PANEL -

- 141 1ST/2ND LAYER EAST WALL BEHIND PANEL,

1ST LAYER/2ND LAYER EAST WALL BEHIND SWITCH GEAR -

- 1ST LAYER 121A, 124,125,127,128,129, 130,131, 132, 133,134, 135, 136,137,138,

1ST LAYER CORRIDOR AT THESE UNITS -

2ND LAYER UNITS 121A,124,125,126,127,128,129,130,131,132,133,134, 135, -

- CORRIDOR 119 1ST LAYER/2ND LAYER BOTH SIDES -
- CORRIDOR 122 1ST LAYER/ 2ND LAYER BOTH SIDES, LID PREROCK -
- CORRIDOR 129 (LID) PREROCK, 1ST/2ND LAYER WALLS,-
- AREA " B" -
- CORRIDOR 109 RC LID/ SCREW PATTERN LID -
- CORRIODR 105 RC LID/SCREW PATTERN LID 109 TO STAIRWAY A -
- LOBBY NORTH & SOUTH WALLS SCREW PATTERN 1 LAYER -

_

Corrective Action Required: 3 SECOND FLOOR

\-AREAS APPROVED-

AREA "E"

RC CHANNEL WALLS AND CEILINGS:

CORRIDORS 219

222,226, 227, 221A,240-245,261-264,265,266,267 -

- RC CHANNEL CORRIDOR 212 CEILING ONLY -
- RC CHANNEL CORRIDOR 229 WALLS & CEILING -
- RC CHANNEL CEILING 220A -

1ST LAYER-222,226

SCREW PATTERN ON FIRST & SECOND LAYERS WALLS CORRIDOR 219 TO ROOM 241, CORRIDOR 222 TO STAIRS

1ST LAYER UNITS: 224A,221A,224A,225A,240,241,242,243,244,245,246, 247,248,249,250,251,252,253,254,255,256,257,258, 259,260,262,263,264,265,266,267,- 2ND LAYER UNITS 221A,224A,225A,236,240,241,242,243, 244,245,246,247,248,249,250,251,252,253,254,255, 256,257,258,259,260,262,263, 264, -

- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -
- 1ST LAYER MECHANCICAL CHASES 2ND FLOOR -
- 2ND LAYER MECHANICAL CHASES 2ND FLOOR/FIRE TAPE COMPLETE OK TO COVER -
- "E" RC CHANNEL CELINGS & WALLS 224A,225A,246,247,248,249,250,251,252,253,254,255,256,257,258,259,260, -
- CORRIDOR 222 2ND LAYER BOTH SIDES -
- CORRIDOR 226 1ST & 2ND LAYER WEST WALL -
- CORRIDOR 226 1ST LAYER EAST WALL & MECH CHASES -
- CORRIDOR 227, CEILING, 1ST LAYER / 2ND LAYER WALLS -
- CORRIDOR 229 CEILING, 1ST LAYER / 2ND LAYER -

:AREA "D":

- CORRIDOR 212 (LID) -

AREA "B"

- CORRIDOR 209 RC LID/ SCREW PATTERN LID -
- CORRIDOR 205 RC LID/ SCREW PATTERN LID 209 TO STAIRWAY A -
- INNER MECH CHASES: 1ST LAYER -

Corrective Action Required:

THIRD FLOOR

AREA "E"

-AREAS APPROVED-

RC CHANNEL - 320A, 321A, 340, 364

RC CHANNEL CORRIDORS- 322,326,327,319
RC CHANNEL CORRIDOR 329 WALLS & CEILING -

- RC CHANNEL

324A,325A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360,365,3 66,367 -

1ST LAYER CEILING- 322, 326 TO ROOM 355.

1STLAYER WALLS CORRIDORS 319 TO ROOM 341,322 TO STAIRS

SCREW PATTERN ROOMS AND FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS:

326,341,342,343,344,345,361,362,363

- RC CHANNEL

324A,346,347,348,349,350,351,352,353,354,355,356,357,358,359,360, -

- 1ST LAYER UNIT 320A, 321A,324A,325A,340, 346,347,348,349,350,351,352,353,354,355,356,357, 358,359,360,364,365,366,367, -

- 2ND LAYER UNIT 320A,321A,324A,325A,340,347,348,349,350,351,352, 353,354,356,357,358,359,360, 364, -
- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -
- 3RD FLOOR MECHANICAL CHASE 1ST LAYER/2ND LAYER COMPLETE -
- CORRIDOR 319 1ST LAYER/2ND LAYER -
- CORRIDOR 322 1ST LAYER/2ND LAYER WALLS -
- CORRIDOR 326 1ST LAYER/2ND LAYER WEST WALL,

1ST LAYER/2ND LAYER EAST WALL -

- CORRIDOR 327 CEILING, 1ST LAYER / 2ND LAYER -
- CORRIDOR 329 LID, 1ST LAYER / 2ND LAYER -
- AREA "D" -
- CORRIDOR 312 RC CHANNEL CEILING -
- CORRIDOR 312 LID -

- UNIT 332 PREROCK LIDS FOR DUCTS LAUNDRY, CLOSETS & BEDROOMS -
- AREA "B" -
- CORRIDOR 309 RC LID -
- CORRIDOR 305 RC LID 309 TO STAIRWAY A -
- INNER MECH CHASES 1ST LAYER -

Corrective Action Required: 5 FOURTH FLOOR

4TH FL- -AREAS APPROVED-

AREA "E" RC CHANNEL AREAS:

-RC CHANNEL UNITS: 420A,437,438-453,

459-462,-424,425A,414A,432,433,434,444,445,446,447,448,449,450,451,452,453,454,455,456,457,463,464 -

- RC CHANNEL CEILING ONLY 420,435,436,437,463,464,465, -
- -RC CORRIDOR 412, 421A, 422, 426, 427,
- -CORRIDOR 429 WALLS & CEILING -
- AREA "E" 4TH FLOOR MECH CHASE OUTSIDE UNITS 448, 450, 451 1ST, 2ND LAYER;

FIRE TAPE COMPLETE -

- BLDG "E" PHASE 2 UNITS:

1ST LAYER :424A,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458 -438, 462, 421A,424A, 425A -

2ND LAYER:

424A,444,445,446,447,448,449,450,451,452,453,454,455,456,457,458, 438, 462,421A,425A -

- NORTH TRASH CHUTE 1ST LAYER/2ND LAYER -
- 420A PREROCK CORRIDOR WALL WALL LAYER -
- CORRIDOR 419 1ST/2ND LAYER;

FIRST & SECOND LAYER CORRIDOR AND DIMISING WALLS: 439,440,441,442,443,459,460,461

- 463,464,465 1ST LAYER -
- CORRIDOR NUMBERS #:
- 429 LID, 1ST / 2ND LAYER -
- ;;439,440,441,442,443,459,460,461;
- WALLS:

422 1ST, 2ND LAYER-;

- 426 1ST, & 2ND LAYER WEST WALL-;
- 426 1ST & 2ND LAYER EAST WALL -
- CORRIDOR 427 CEILING, 1ST/2ND LAYER -
- 417 RC CHANNEL CEILING -
- " D"
- CORRIDOR 412 RC CHANNEL LID, CEILING COMPLETE -

-CORRIDOR 409 RC LID / SCREW PATTERN LID -

- CORRIDOR 405 RC LID / SCREW PATTERN LID 409 TO STAIRWAY A -

- INNER MECH CHASES 1ST LAYER -

Corrective Action Required:

6 STAIR TOWER 1 STAIR TOWER

STAIR TOWER 107 "A" SOUTH AREA "B"

AREAS OK:

-1ST LAYER SHEATHING TO 3RD FLOOR; -2ND LAYER SHEATHING TO 3RD FLOOR:

- 1ST LAYER/2ND LAYER SHEATHING 4TH FLOOR -

Corrective Action Required:

7 ELEVATOR 2

ELEVATOR 118 "B" WEST CENTER AREAS INSPECTED:

AREAS OK:

-SHEATHING ON NORTH AND SOUTH WALLS (TYPE A)

-FIRST LAYER SHEATHING ON (TYPE E2) WALLS FIRST AND SECOND FLOORS -

- 2ND LAYER "B" ELEVATOR WALLS

- 1ST LAYER "B" 3RD & 4TH FLOOR SHAFT WALL-- 2ND LAYER "B" 3RD & 4TH FLOOR SHAFT WALL-

Corrective Action Required:

8 ELEVATOR 3

ELEVATOR 128 "C" NORTH EAST-AREAS INSPECTED:

- ELEVATOR 128" C " -

- 1ST LAYER WEST WALL 2ND,3RD,4TH FLOORS -

- 2ND LAYER WEST WALL 2ND, 3RD & 4TH FLOORS-

- 1ST LAYER 4TH FLOOR SOUTH WALL SHAFT & EXTERIOR WALL -

- ELEVATOR C 4TH FLOOR SHAFT WALL 2ND LAYER CEILING TO 8', 8' TO ACCESS

HOLE IN CORRIDOR -

- ELEVATOR SHAFT 1ST LAYER 4TH FLOOR, 3RD FLOOR, 2ND FLOOR -

- ELEVATOR SHAFT 2ND LAYER 4TH, 3RD, 2ND -

Corrective Action Required:

9 STAIR TOWER 2

STAIR TOWER 113 "B" WEST CENTER AREAS INSPECTED:

Corrective Action Required:

10 STAIR TOWER 3

STAIR TOWER 123 "C" NORTH

AREAS INSPECTED:

- 1ST LAYER FLOORS 1 THRU 4 - 2ND LAYER FLOORS 1 THRU 4 -

- CEILING -

- RC CHANNEL CEILING -

Corrective Action Required:

11 ELEVATOR 1

ELEVATOR 102 "A" SOUTH CENTER AREAS INSPECTED:

Comments: